

National Transportation Safety Board Aviation Accident Final Report

Location: HONOLULU, HI Accident Number: LAX84LA401

Date & Time: 07/17/1984, 0600 HST Registration: N21S

Aircraft: BEECH H18S Aircraft Damage: Destroyed

Defining Event: Injuries: 1 None

Flight Conducted Under: Part 135: Air Taxi & Commuter - Non-scheduled

Analysis

DURING TAKEOFF AT ABOUT 50 FT AGL & 4,000 FT DOWN RWY 4R, THE RIGHT ENG LOST POWER. ACCORDING TO THE PLT, HIS AIRSPEED WAS 105 MPH & THE RIGHT ENG 'POPPED' BEFORE IT LOST POWER. HE ALSO STATED THAT POWER ON THE LEFT ENG DETERIORATED AFTER THE THE RIGHT PROP WAS FEATHERED. THE ACFT WENT INTO A RIGHT BANK & THE PLT MAINTAINED CONTROL OF THE ACFT UNTIL IMPACT WITH THE WATER. EXAMINATION OF THE RIGHT ENG REVEALED THAT THE RIGHT MAGNETO, AMERICAN BOSCH SB9RU-3, SER #B88470, WAS NOT TIMED CORRECTLY. DISASSEMBLY OF THE MAGNETO REVEALED THAT ALL EXCEPT 11 DISTRIBUTOR GEAR TEETH WERE STRIPPED OFF. AT THE TIME OF THE POWER LOSS OF THE RIGHT ENG, ABOUT 5,000 FT OF RWY WAS REMAINING.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - MECH FAILURE/MALF

Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

1. (C) IGNITION SYSTEM, MAGNETO - FAILURE, TOTAL

Occurrence #2: FORCED LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Occurrence #3: DITCHING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

2. (C) IN-FLIGHT PLANNING/DECISION - IMPROPER - PILOT IN COMMAND

3. (C) EMERGENCY PROCEDURE - IMPROPER - PILOT IN COMMAND

4. (C) ABORTED TAKEOFF - NOT PERFORMED - PILOT IN COMMAND

Page 2 of 5 LAX84LA401

Factual Information

Pilot Information

Certificate:	Airline Transport; Flight Instructor; Commercial	Age:	51, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	Seatbelt
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane Multi-engine; Helicopter; Instrument Helicopter	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/waivers/lim.	Last FAA Medical Exam:	06/10/1984
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	4772 hours (Total, all aircraft), 99 hours (Total, this make and model), 3091 hours (Pilot In Command, all aircraft), 94 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	BEECH	Registration:	N21S
Model/Series:	H18S H18S	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	BA690
Landing Gear Type:	Retractable - Tricycle	Seats:	2
Date/Type of Last Inspection:	07/05/1984, AAIP	Certified Max Gross Wt.:	10100 lbs
Time Since Last Inspection:	14 Hours	Engines:	2 Reciprocating
Airframe Total Time:	10511 Hours	Engine Manufacturer:	P&W
ELT:	Installed, activated	Engine Model/Series:	R985AN143
Registered Owner:	PACIFIC AIR EXPRESS, INC.	Rated Power:	450 hp
Operator:	PACIFIC AIR EXPRESS, INC.	Operating Certificate(s) Held:	On-demand Air Taxi (135)

Page 3 of 5 LAX84LA401

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Dawn
Observation Facility, Elevation:	HNL, 13 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	0600 HST	Direction from Accident Site:	310°
Lowest Cloud Condition:	Scattered / 1500 ft agl	Visibility	15 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	4 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	270°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	24°C
Precipitation and Obscuration:			
Departure Point:		Type of Flight Plan Filed:	Company VFR
Destination:	LIHUE, HI (LIH)	Type of Clearance:	None
Departure Time:	0600 HST	Type of Airspace:	Class B

Airport Information

Airport:	HONOLULU INTL	Runway Surface Type:	Asphalt
Airport Elevation:	10 ft	Runway Surface Condition:	Dry
Runway Used:	4R	IFR Approach:	None
Runway Length/Width:	9000 ft / 150 ft	VFR Approach/Landing:	Forced Landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Destroyed
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	M.	J PYATT	Report Date:
Additional Participating Persons:			
Publish Date:			
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at publing@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/ .		

Page 4 of 5 LAX84LA401

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 5 of 5 LAX84LA401