

# National Transportation Safety Board Aviation Accident Final Report

Location: GASTON, SC Accident Number: ATL89FA165

Date & Time: 06/20/1989, 1642 EDT Registration: N78TW

Aircraft: BEECH B-60 Aircraft Damage: Destroyed

Defining Event: Injuries: 4 Fatal

Flight Conducted Under: Part 91: General Aviation - Personal

## **Analysis**

AFTER OBTAINING A WEATHER BRIEFING IN WHICH HE WAS INFORMED OF THUNDERSTORMS AND CURRENT SIGMETS FOR HIS INTENDED ROUTE OF FLIGHT, THE PILOT ELECTED TO DEPART HIS HOME AIRPORT ON A PERSONAL FLIGHT. AT THE TIME OF DEPARTURE, WITNESSES INDICATED THE PRESENCE OF THUNDERSTORMS ADJACENT TO THE AIRPORT. AFTER TRYING TO OBTAIN HIS IFR CLEARANCE FROM CHARLOTTE, THE PILOT WAS ISSUED HIS IFR CLEARANCE WHEN APPROACHING COLUMBIA, SC. THE PILOT HAD DEVIATED AROUND AT LEAST ONE THUNDERSTORM WHILE APPROACHING COLUMBIA. THE PILOT HAD BEEN CLEARED TO CLIMB TO HIS REQUESTED ALTITUDE OF 17,000 FEET AND HAD REACHED 16,400 WHEN THE RADAR RETURN WAS OBSERVED TO INDICATE A DESCENT AND THEN WAS LOST. WITNESSES ON THE GROUND REPORTED SEEING THE AIRPLANE EXIT THE CLOUDS IN FLAMES. THE EVIDENCE INDICATED THAT THE HORIZONTAL TAIL HAD SEPARATED FOLLOWED BY THE WINGS AND OTHER COMPONENTS OF THE AIRPLANE. NO EVIDENCE OF SEPARATION DUE TO STRUCTURAL WEAKENING FROM HEATING WAS FOUND.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT EXERCISED QUESTIONABLE JUDGEMENT IN INITIATING A FLIGHT INTO AN AREA OF KNOWN THUNDERSTORMS. FURTHER, EITHER DELIBERATELY OR INADVERTANTLY ENTERED A THUNDERSTORM AND OVERSTRESSED THE AIRFRAME STRUCTURE RESULTING IN AN INFLIGHT SEPARATION OF THE AERODYNAMIC SURFACES.

### **Findings**

Occurrence #1: IN FLIGHT ENCOUNTER WITH WEATHER

Phase of Operation: CLIMB - TO CRUISE

#### **Findings**

- 1. WEATHER CONDITION THUNDERSTORM, LEVEL III
- 2. WEATHER EVALUATION INADEQUATE PILOT IN COMMAND
- 3. (C) FLIGHT INTO KNOWN ADVERSE WEATHER ATTEMPTED PILOT IN COMMAND
- 4. (C) IN-FLIGHT PLANNING/DECISION POOR PILOT IN COMMAND
- 5. OVERCONFIDENCE IN PERSONAL ABILITY PILOT IN COMMAND
- 6. IN FLIGHT WEATHER AVOIDANCE ASSISTANCE NOT USED PILOT IN COMMAND
- 7. OVERCONFIDENCE IN AIRCRAFT'S ABILITY PILOT IN COMMAND

-----

Occurrence #2: LOSS OF CONTROL - IN FLIGHT Phase of Operation: DESCENT - UNCONTROLLED

#### **Findings**

8. REMEDIAL ACTION - NOT PERFORMED - PILOT IN COMMAND

9. AIRCRAFT CONTROL - NOT MAINTAINED - PILOT IN COMMAND

-----

Occurrence #3: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION

Phase of Operation: DESCENT - UNCONTROLLED

#### **Findings**

10. (C) DESIGN STRESS LIMITS OF AIRCRAFT - EXCEEDED - PILOT IN COMMAND

-----

Occurrence #4: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT - UNCONTROLLED

Page 2 of 5 ATL89FA165

## **Factual Information**

### **Pilot Information**

Certificate:	Private	Age:	49, Male
Airplane Rating(s):	Multi-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	Yes
Medical Certification:	Class 3 Valid Medicalw/waivers/lim.	Last FAA Medical Exam:	01/10/1989
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	1290 hours (Total, all aircraft), 26 hours (Total, this make and model), 1010 hours (Pilot In Command, all aircraft), 17 hours (Last 90 days, all aircraft), 6 hours (Last 30 days, all aircraft)		

## Aircraft and Owner/Operator Information

Aircraft Make:	BEECH	Registration:	N78TW
Model/Series:	B-60 B-60	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	P-445
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	01/13/1989, Annual	Certified Max Gross Wt.:	6725 lbs
Time Since Last Inspection:	21 Hours	Engines:	2 Reciprocating
Airframe Total Time:	1669 Hours	Engine Manufacturer:	LYCOMING
ELT:		Engine Model/Series:	TIO-5410E1C4
Registered Owner:	MAURICE J WALSH, III	Rated Power:	380 hp
Operator:	MAURICE J. WALSH, III	Operating Certificate(s) Held:	None

Page 3 of 5 ATL89FA165

Meteorological Information and Flight Plan

Conditions at Accident Site:	Instrument Conditions	Condition of Light:	Day
Observation Facility, Elevation:	CAE, 236 ft msl	Distance from Accident Site:	9 Nautical Miles
Observation Time:	1650 EDT	Direction from Accident Site:	325°
Lowest Cloud Condition:	Unknown / 0 ft agl	Visibility	10 Miles
Lowest Ceiling:	Broken / 4000 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	110°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	24°C / 21°C
Precipitation and Obscuration:			
Departure Point:	GASTONIA, NC (0A6)	Type of Flight Plan Filed:	IFR
Destination:	FORT PIERCE, FL (FPR)	Type of Clearance:	IFR
Departure Time:	1600 EDT	Type of Airspace:	Class E

## **Airport Information**

Airport:	COLUMBIA METRO (CAE)	Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

## Wreckage and Impact Information

Crew Injuries:	1 Fatal	Aircraft Damage:	Destroyed
Passenger Injuries:	3 Fatal	Aircraft Fire:	In-Flight and On-Ground
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	4 Fatal	Latitude, Longitude:	

## **Administrative Information**

Investigator In Charge (IIC):	WALTER G STINER	Report Date:	07/11/1990
Additional Participating Persons:	JAMES MALEK; COLUMBIA, SC  JAMES STABLEY; WILLIAMSPORT, PA G D STAAB; WICHITA, KS		
Publish Date:			
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at <a href="mailto:publicq@ntsb.gov">publicq@ntsb.gov</a> , or at 800-877-6799. Dockets released after this date are available at <a href="http://dms.ntsb.gov/pubdms/">http://dms.ntsb.gov/pubdms/</a> .		

Page 4 of 5 ATL89FA165

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 5 of 5 ATL89FA165