

National Transportation Safety Board Aviation Accident Final Report

Location: AIALAK BAY, AK Accident Number: ANC90FA101

Date & Time: 06/25/1990, 1430 AKD Registration: N9985M

Aircraft: CESSNA 207A Aircraft Damage: Destroyed

Defining Event: 5 Fatal

Flight Conducted Under: Part 135: Air Taxi & Commuter - Non-scheduled

Analysis

TWO AIRPLANES DEPARTED SEWARD WITHIN MINUTES OF EACH OTHER ON A LOCAL FLIGHTSEEING TRIP, AND THEIR FLIGHT ROUTES WERE TO BE THE SAME. AFTER REACHING AIALAK BAY, THIS AIRPLANE PASSED THE OTHER AND STARTED THE RETURN TRIP TO SEWARD. THE PASS THEY WOULD NORMALLY USE WAS OBSCURED BY CLOUDS. THE PENINSULA THAT SEPARATED AIALAK BAY AND SEWARD WAS THE ONLY PART OF LAND THAT WAS OBSCURED BY WEATHER. THE BASES OF THE CLOUDS WERE AT 1200 FEET MSL. THE AIRPLANE WAS LOCATED ON THE NORTHEAST SIDE, AT THE 2700 FOOT LEVEL OF A MOUNTAIN, AND THE WRECKAGE WAS SCATTERED ALONG 330 DEGREES. THE PILOT HAD BEEN HIRED LESS THAN 2 MONTHS BEFORE THE ACCIDENT AS A GROUND HANDLER AND FUELER, AND FOR PILOT TRAINING. TWO DAYS BEFORE THE ACCIDENT HE WAS AUTHORIZED TO FLY PART 135 FLIGHTSEEING TRIPS.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT-IN-COMMAND'S ATTEMPT TO FLY UNDER VISUAL FLIGHT RULES WHILE IN INSTRUMENT METEOROLOGICAL CONDITIONS. CONTRIBUTING FACTORS TO THE ACCIDENT WERE THE LOW CEILING AND SURROUNDING MOUNTAINOUS TERRAIN.

Findings

Occurrence #1: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: CRUISE

Findings

1. (F) TERRAIN CONDITION - MOUNTAINOUS/HILLY

2. (F) WEATHER CONDITION - LOW CEILING

3. (C) VFR FLIGHT INTO IMC - CONTINUED - PILOT IN COMMAND

Page 2 of 5 ANC90FA101

Factual Information

Pilot Information

Certificate:	Commercial	Age:	42, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	Yes
Medical Certification:	Class 2 Invalid Medical for flight	Last FAA Medical Exam:	08/16/1988
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	540 hours (Total, all aircraft), 510 hours (Pilot In Command, all aircraft), 100 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N9985M
Model/Series:	207A 207A	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	20700775
Landing Gear Type:	Tricycle	Seats:	6
Date/Type of Last Inspection:	06/18/1990, 100 Hour	Certified Max Gross Wt.:	3800 lbs
Time Since Last Inspection:	8 Hours	Engines:	1 Reciprocating
Airframe Total Time:	3391 Hours	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	IO-520-F
Registered Owner:	TRAIL LAKE FLYING SERVICE, INC	Rated Power:	300 hp
Operator:	TRAIL LAKE FLYING SERVICE, INC	Operating Certificate(s) Held:	On-demand Air Taxi (135)
Operator Does Business As:		Operator Designator Code:	TLFA

Page 3 of 5 ANC90FA101

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	0000	Direction from Accident Site:	0°
Lowest Cloud Condition:	Unknown / 0 ft agl	Visibility	10 Miles
Lowest Ceiling:	Overcast / 1200 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	15 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	160°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	13°C
Precipitation and Obscuration:			
Departure Point:	SEWARD, AK (SWD)	Type of Flight Plan Filed:	Company VFR
Destination:		Type of Clearance:	None
Departure Time:	1305 ADT	Type of Airspace:	Class G

Airport Information

Airport:	SEWARD (SWD)	Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 Fatal	Aircraft Damage:	Destroyed
Passenger Injuries:	4 Fatal	Aircraft Fire:	On-Ground
Ground Injuries:	N/A	Aircraft Explosion:	On-Ground
Total Injuries:	5 Fatal	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	GEORGE	KOBELNYK	Report Date:	12/14/1992
Additional Participating Persons:				
Publish Date:				
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at publing@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/ .			

Page 4 of 5 ANC90FA101

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 5 of 5 ANC90FA101