

National Transportation Safety Board Aviation Accident Final Report

Location: BROOMFIELD, CO Accident Number: DEN93LA013

Date & Time: 11/20/1992, 1840 MST Registration: N473FW

Aircraft: MITSUBISHI MU-2B-25 Aircraft Damage: Substantial

Defining Event: Injuries: 4 None

Flight Conducted Under: Part 91: General Aviation - Business

Analysis

IN PREPARATION FOR A CROSS COUNTRY FLIGHT WITH TAKEOFF OCCURRING DURING A SNOW STORM, THE AIRCRAFT WAS LOADED IN THE HANGAR AND TOWED OUT BY FBO PERSONNEL. FOLLOWING THE TOW, THE TORQUE LINK WAS NOT PROPERLY CONNECTED AND SEPARATED DURING THE TAKEOFF RUN. DUE TO A LOSS OF NOSE WHEEL STEERING, THE TAKEOFF WAS ABORTED. THE AIRCRAFT DEPARTED THE SIDE OF THE RUNWAY DURING THE ABORT AND THE NOSE WHEEL WAS SHEARED OFF CAUSING DAMAGE TO BOTH ENGINES, WINGS, THE FUSELAGE, AND LANDING GEAR.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: A FAILURE BY FBO PERSONNEL TO PROPERLY CONNECT THE NOSE WHEEL TORQUE LINK AFTER TOWING THE AIRCRAFT.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: TAKEOFF - ROLL/RUN

Findings

1. WEATHER CONDITION - SNOW

2. (C) LANDING GEAR, STEERING SYSTEM - DISCONNECTED

3. (C) PROPER ASSISTANCE - NOT PERFORMED - FBO PERSONNEL

Occurrence #2: NOSE GEAR COLLAPSED Phase of Operation: TAKEOFF - ABORTED

Findings

4. TERRAIN CONDITION - SNOW COVERED

Page 2 of 5 DEN93LA013

Factual Information

Pilot Information

Certificate:	Airline Transport; Flight Instructor	Age:	44, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane Multi-engine; Airplane Single-engine; Instrument Airplane	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	10/13/1992
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	13753 hours (Total, all aircraft), 4200 hours (Total, this make and model), 1346 hours (Pilot In Command, all aircraft), 59 hours (Last 90 days, all aircraft), 31 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	MITSUBISHI	Registration:	N473FW
Model/Series:	MU-2B-25 MU-2B-25	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	269
Landing Gear Type:	Retractable - Tricycle	Seats:	7
Date/Type of Last Inspection:	09/23/1991, 100 Hour	Certified Max Gross Wt.:	9200 lbs
Time Since Last Inspection:	60 Hours	Engines:	2 Turbo Prop
Airframe Total Time:	3406 Hours	Engine Manufacturer:	GARRETT
ELT:	Installed, not activated	Engine Model/Series:	TPE331-6
Registered Owner:	WAYNE C. MUHLER	Rated Power:	725 hp
Operator:	WAYNE C. MUHLER	Operating Certificate(s) Held:	None
Operator Does Business As:	MUHL AIR	Operator Designator Code:	

Page 3 of 5 DEN93LA013

Meteorological Information and Flight Plan

Conditions at Accident Site:	Instrument Conditions	Condition of Light:	Night/Dark
Observation Facility, Elevation:	BJC, 5657 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	1855 MST	Direction from Accident Site:	70°
Lowest Cloud Condition:	Unknown / 0 ft agl	Visibility	0 Miles
Lowest Ceiling:	Obscured / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	12 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	10°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	0°C / -7°C
Precipitation and Obscuration:			
Departure Point:	(BJC)	Type of Flight Plan Filed:	IFR
Destination:	LAS VEGAS, NV (LAS)	Type of Clearance:	IFR
Departure Time:	1840 MST	Type of Airspace:	Class E

Airport Information

Airport:	JEFFERSON COUNTY (BJC)	Runway Surface Type:	Asphalt
Airport Elevation:	5658 ft	Runway Surface Condition:	Slush covered; Snowwet
Runway Used:	29	IFR Approach:	
Runway Length/Width:	9000 ft / 100 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	4 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	NORMAN F WIEMEYER	Report Date:	09/14/1993
Additional Participating Persons:	BUDDY MAKIN; DENVER, CO		
Publish Date:			
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at publing@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/ .		

Page 4 of 5 DEN93LA013

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 5 of 5 DEN93LA013