



Aviation Investigation Final Report

Location:	Auburn, California	Accident Number:	WPR20FA077
Date & Time:	January 24, 2020, 09:56 Local	Registration:	N50249
Aircraft:	Stinson V77	Aircraft Damage:	Destroyed
Defining Event:	Loss of engine power (total)	Injuries:	2 Fatal, 1 Serious
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

The pilot departed on a local flight with two passengers. Several witnesses reported that they heard the airplane's engine backfiring and sputtering and subsequently heard the engine quit. The surviving passenger, who was seated in the front right seat, stated that the engine lost power and there was nowhere to land. The airplane subsequently impacted heavily wooded terrain about 1 mile from the departure airport.

Postaccident examination of the engine revealed that the No. 7 cylinder intake valve was stuck open. The No. 2 cylinder front spark plug was defective, and the Nos. 2- and 4-cylinders' ignition wires were frayed, worn, and displayed arcing, which likely led to erratic operation or a lack of ignition in these two cylinders. The culmination of these issues most likely led to the engine running rough, backfiring, and subsequently losing total power.

An annual inspection was accomplished on the airframe and engine about 2 months before the accident. General maintenance practices and the inspection should have identified the anomalies that were found during the postaccident engine examination.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

A total loss of engine power due to a combination of mechanical engine anomalies. Contributing to the accident was inadequate maintenance that failed to identify the engine anomalies.

Findings

Aircraft	Recip eng cyl section - Failure
Aircraft	Recip eng wiring - Damaged/degraded
Aircraft	Spark plugs/igniters - Damaged/degraded
Environmental issues	Mountainous/hilly terrain - Contributed to outcome
Personnel issues	Scheduled/routine maintenance - Maintenance personnel

Factual Information

History of Flight

Enroute	Loss of engine power (total) (Defining event)
Enroute	Collision with terr/obj (non-CFIT)

Pilot Information

Certificate:	Commercial	Age:	55,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	Yes
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	May 10, 2019
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	(Estimated) 650 hours (Total, all aircraft)		

Pilot-rated passenger Information

Certificate:	Private	Age:	Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Rear
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	Yes
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	February 21, 2018
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	(Estimated) 1532 hours (Total, all aircraft)		

Pilot-rated passenger Information

Certificate:	Private	Age:	30,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 2 None	Last FAA Medical Exam:	February 21, 2019
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	(Estimated) 250 hours (Total, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Stinson	Registration:	N50249
Model/Series:	V77 No Series	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	77-458
Landing Gear Type:	Tailwheel	Seats:	
Date/Type of Last Inspection:	December 1, 2019 Annual	Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Pratt & Whitney
ELT:	Installed	Engine Model/Series:	985
Registered Owner:		Rated Power:	450 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KAUN,1531 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	09:55 Local	Direction from Accident Site:	251°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.19 inches Hg	Temperature/Dew Point:	14°C / 10°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Auburn, CA (AUN)	Type of Flight Plan Filed:	None
Destination:	Auburn, CA (AUN)	Type of Clearance:	None
Departure Time:	09:40 Local	Type of Airspace:	

Wreckage and Impact Information

Crew Injuries:	1 Fatal	Aircraft Damage:	Destroyed
Passenger Injuries:	1 Fatal, 1 Serious	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	2 Fatal, 1 Serious	Latitude, Longitude:	38.959445,-121.06583(est)

Administrative Information

Investigator In Charge (IIC):	Nixon, Albert		
Additional Participating Persons:	Joseph Mitchell; Federal Aviation Administration; Sacramento, CA		
Original Publish Date:	May 19, 2022	Investigation Class:	3
Note:			
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=100856		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).