

National Transportation Safety Board  
Washington, DC 20594

Printed on : 12/05/2013 08:14:24 AM

Brief of Accident

Adopted 09/05/2013

ERA12FA423  
File No. 31583                      06/30/2012                      Dalton ,GA                      Aircraft Reg No. N33CG                      Time (Local): 16:20 EDT

Make/Model: Piper/PA-31P  
Engine Make/Model: Lycoming / TIGO-541SER  
Aircraft Damage: Substantial  
Number of Engines: 2  
Operating Certificate(s): None  
Type of Flight Operation: Personal  
Reg. Flight Conducted Under: Part 91: General Aviation

	Fatal	Serious	Minor/None
Crew	1	0	0
Pass	0	0	0

Last Depart. Point: Same as Accident/Incident Location  
Destination: Same as Accident/Incident Location  
Airport Proximity: Off Airport/Airstrip

Condition of Light: Day  
Weather Info Src: Weather Observation Facility  
Basic Weather: Visual Conditions  
Lowest Ceiling: None  
Visibility: 10.00 SM  
Wind Dir/Speed: Light and Variable  
Temperature (°C): 39  
Precip/Obscuration: No Obscuration; No Precipitation

Pilot-in-Command                      Age: 52  
Certificate(s)/Rating(s)  
Private; Multi-engine Land; Single-engine Land  
Instrument Ratings  
Airplane

Flight Time (Hours)  
Total All Aircraft: 1685  
Last 90 Days: Unk/Nr  
Total Make/Model: Unk/Nr  
Total Instrument Time: Unk/Nr

\*\*\* Note: NTSB investigators either traveled in support of this investigation or conducted a significant amount of investigative work without any travel, and used data obtained from various sources to prepare this aircraft accident report. \*\*\*

According to a friend of the pilot, the pilot was taking the airplane to have an annual inspection completed. The friend assisted the pilot before departure and watched as the airplane departed. He did not notice any anomalies with the airplane during the takeoff or the climbout. According to a witness in the vicinity of the accident site, he heard the airplane coming toward him, and it was flying very low. He looked up and saw the airplane approximately 200 feet over his house and descending toward the trees. As he watched the airplane, he noticed that the right propeller was not turning, and the right engine was not running. He stated that the left engine sounded as if it was running at full power. The airplane pitched up to avoid a power line and rolled to the right, descending below the tree line. A plume of smoke and an explosion followed.

Examination of the right propeller assembly revealed evidence of significant frontal impact. The blades were bent but did not have indications of rotational scoring; thus they likely were not rotating at impact. One preload plate impact mark indicated that the blades were at an approximate 23-degree angle; blades that are feathered are about 86 degrees. Due to fire and impact damage of the right engine and related system components, the reason for the loss of power could not be determined. An examination of the airframe and left engine revealed no mechanical malfunctions or failures that would have precluded normal operation.

Brief of Accident (Continued)

ERA12FA423  
File No. 31583

06/30/2012

Dalton ,GA

Aircraft Reg No. N33CG

Time (Local): 16:20 EDT

---

A review of the airplane maintenance logbooks revealed that the annual inspection was 12 days overdue. According to Lycoming Service Instruction No. 1009AS, the recommended time between engine overhaul is 1,200 hours or 12 years, whichever occurs first. A review of the right engine maintenance logbook revealed that the engine had accumulated 1,435 hours since major overhaul and that neither engine had been overhauled within the preceding 12 years.

Although the propeller manufacturer recommends that the propeller be feathered before the engine rpm drops below 1,000 rpm, a review of the latest revision of the pilot operating handbook (POH) revealed that the feathering procedure for engine failure did not specify this. It is likely that the pilot did not feather the right propeller before the engine reached the critical 1,000 rpm, which prevented the propeller from engaging in the feathered position.

Updated at Sep 5 2013 2:27PM

Brief of Accident (Continued)

ERA12FA423  
File No. 31583

06/30/2012

Dalton ,GA

Aircraft Reg No. N33CG

Time (Local): 16:20 EDT

---

OCCURRENCES

Initial climb - Loss of engine power (partial)  
Emergency descent - Off-field or emergency landing  
Emergency descent - Loss of control in flight  
Uncontrolled descent - Collision with terr/obj (non-CFIT)

FINDINGS

Aircraft-Aircraft power plant-Engine (reciprocating)-(general)-Failure  
Not determined-Not determined-(general)-(general)-Unknown/Not determined  
Aircraft-Aircraft propeller/rotor-Propeller system-Propeller feather/reversing-Incorrect use/operation - C  
Organizational issues-Management-Policy/procedure-Adequacy of policy/proc-Manufacturer - F  
Personnel issues-Action/decision-Action-Delayed action-Pilot - C  
Aircraft-Aircraft oper/perf/capability-Performance/control parameters-Altitude-Attain/maintain not possible - C  
Aircraft-Aircraft power plant-Power plant-(general)-Not serviced/maintained

Findings Legend: (C) = Cause, (F) = Factor

---

The National Transportation Safety Board determines the probable cause(s) of this accident as follows:

The pilot's failure to maintain airplane control following loss of power in the right engine for reasons that could not be determined because of fire and impact damage. Contributing to the accident was the pilot's delayed feathering of the right propeller following the loss of engine power and the lack of specific emergency procedures in the pilot operating handbook indicating the need to feather the propellers before engine rpm falls below 1,000 rpm.