

**Aviation Safety Investigation Report
198703483**

Cessna 402-C

21 June 1987

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

warnings. During this time he would not have been monitoring the primary flight attitude indicator, and would have had no external visual references. It was also possible that, if for some reason the pilot was not monitoring his flight instruments as the aircraft entered the fog, he suffered a form of spatial disorientation known as the somatogravic illusion. This illusion has been identified as a major factor in many similar accidents following night takeoffs. As an aircraft accelerates, the combination of the forces of acceleration and gravity induce a sensation that the aircraft is pitching nose-up. The typical reaction of the pilot is to counter this apparent pitch by gently applying forward elevator control, which can result in the aircraft descending into the ground. In this particular case, the pilot would probably have been more susceptible to disorientating effects, because he was suffering from a bronchial or influenzal infection. Although all of the above were possible explanations for the accident, there was insufficient evidence available to form a firm conclusion. The precise cause of the accident remains undetermined. POSSIBLE

Significant Factors:

It is considered that some of the following factors may have been relevant to the development of the accident

1. The pilot was making a hurried DEPARTURE. It is possible that he did not correctly set the elevator trim and/or the engines may not have reached normal operating temperatures before the takeoff was commenced.
2. Shortly after liftoff the aircraft entered a fog bank, which would have deprived the pilot of external visual references.
3. The aircraft had a defective engine fire warning system. Had the system activated it may have distracted the pilot at a critical stage of flight.
4. The aircraft might have suffered an electric elevator trim malfunction, or an internal fire, leading to loss of control of the aircraft.
5. The pilot may have experienced the somatogravic illusion and inadvertently flown the aircraft into the ground. The chances of such an illusion occurring would have been increased because the pilot was evidently suffering from an infection.

Reccomendations:

During the investigation it was determined that neither the nursing sister nor the ambulance officer was wearing a seat belt. Expert medical opinion indicated that had belts been worn those occupants may have survived the accident. It is recommended that the Civil Aviation Authority brings this matter to the attention of the aviation industry in general, and to operators of aero-medical aircraft in particular. It is also recommended that the Civil Aviation Authority publish further information to remind pilots of sensory problems which can occur during night operations.