

# National Transportation Safety Board Aviation Accident Final Report

Location: Deadhorse, AK Accident Number: ANC91GAMS1

Date & Time: 10/11/1990, 1730 AKD Registration: N45Q

Aircraft: Gulfstream Aerospace 690C Aircraft Damage: Destroyed

Defining Event: Injuries: 3 Fatal

Flight Conducted Under: Public Aircraft

## **Analysis**

The airplane with a certificated airline transport pilot and two passengers aboard departed on a US Department of the Interior, public use flight over the Arctic Ocean. The purpose of the flight was to locate radio collared polar bears. Radar contact with the airplane was lost while it was maneuvering at 22,000 feet msl about 200 miles from shore. The airplane did not reach the intended destination, and neither the airplane nor its occupants were located during an extensive search.

# **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: Missing aircraft.

### **Findings**

Occurrence #1: MISSING AIRCRAFT Phase of Operation: UNKNOWN

**Findings** 

1. REASON FOR OCCURRENCE UNDETERMINED

### **Factual Information**

On October 11, 1990, about 1730 Alaska daylight time, a wheel-equipped Gulfstream Aerospace 690C Turbine Commander airplane, N45Q, is presumed to have crashed in the Arctic Ocean about 200 miles north-northwest of Deadhorse, Alaska. Neither the airplane nor its occupants have been located. The airplane was being operated by the US Department of the Interior, as a visual flight rules (VFR) public use local game management flight, for the purpose of locating radio collared polar bears, when the accident occurred. The airplane, registered to Bowhead Equipment Company of Seattle, Washington, and operated by Alaska Helicopters, Inc. of Anchorage, Alaska, is presumed to have been destroyed. The certificated airline transport pilot, and the two passengers, are presumed to have received fatal injuries. Visual meteorological conditions prevailed at the point of departure. A VFR flight plan was filed by the pilot for a 5.5 hour flight originating and terminating at Deadhorse. The accident flight originated at the Deadhorse Airport about 1429.

According to information received from the Federal Aviation Administration's (FAA), Air Route Traffic Control Center, radar contact was lost with the accident airplane while it was maneuvering at 22,000 feet msl, about 200 miles north-northwest of Deadhorse.

The accident airplane did not reach the intended destination of Deadhorse, and was not located at any airport. The FAA issued an alert notice (ALNOT) at 2221. Search personnel began an extensive search effort that included a high altitude, special radar-equipped airplane, surface vessels, and ground search personnel. The search was suspended on October 26, 1990.

#### **Pilot Information**

Certificate:	Airline Transport	Age:	50, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land; Single-engine Sea	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane Multi-engine; Airplane Single-engine	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/waivers/lim.	Last FAA Medical Exam:	03/26/1990
Occupational Pilot:		Last Flight Review or Equivalent:	10/02/1991
Flight Time:	17500 hours (Total, all aircraft), 1200 hours (Total, this make and model), 16000 hours (Pilot In Command, all aircraft), 153 hours (Last 90 days, all aircraft), 10 hours (Last 24 hours, all aircraft)		

Page 2 of 4 ANC91GAMS1

Aircraft and Owner/Operator Information

Aircraft Make:	Gulfstream Aerospace	Registration:	N45Q
Model/Series:	690C	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	11623
Landing Gear Type:	Retractable - Tricycle	Seats:	8
Date/Type of Last Inspection:	10/01/1991, Continuous Airworthiness	Certified Max Gross Wt.:	10325 lbs
Time Since Last Inspection:	13.8 Hours	Engines:	2 Turbo Prop
Airframe Total Time:	3115 Hours as of last inspection	Engine Manufacturer:	Garrett
ELT:	Installed, not activated	Engine Model/Series:	TPE331-5-254K
Registered Owner:	Bowhead Equipment Comapny	Rated Power:	718 hp
Operator:	Alaska Helicopters Inc	Operating Certificate(s) Held:	Large Helicopter (127); Ondemand Air Taxi (135)
Operator Does Business As:		Operator Designator Code:	ERCL

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day	
Observation Facility, Elevation:		Distance from Accident Site:		
Observation Time:		Direction from Accident Site:		
Lowest Cloud Condition:		Visibility		
Lowest Ceiling:		Visibility (RVR):		
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	1	
Wind Direction:		Turbulence Severity Forecast/Actual:	/	
Altimeter Setting:		Temperature/Dew Point:		
Precipitation and Obscuration:				
Departure Point:	Deadhorse, AK (PALP)	Type of Flight Plan Filed:	VFR	
Destination:	Deadhorse, AK (PALP)	Type of Clearance:	None	
Departure Time:	1429 ADT	Type of Airspace:	Class G	

# Wreckage and Impact Information

Crew Injuries:	1 Fatal	Aircraft Damage:	Destroyed
Passenger Injuries:	2 Fatal	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 Fatal	Latitude, Longitude:	70.333333, -150.933333

Page 3 of 4 ANC91GAMS1

### Administrative Information

Investigator In Charge (IIC): James Michelangelo Report Date: 05/30/2003

Additional Participating Persons: ; Federal Aviation Administration; Fairbanks, AK

Publish Date:

Investigation Docket: NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at <a href="http://dms.ntsb.gov/pubdms/">http://dms.ntsb.gov/pubdms/</a>.

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.