

**Aviation Safety Investigation Report
199001981**

Cessna 501

22 April 1990

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

not attempted to deploy the drag chute immediately the nosewheel was on the ground, and had not applied unmodulated pressure to the anti-skid braking system. These measures are required by the manufacturer to obtain maximum performance. It was found that the drag chute canister lid had been sealed with tank sealant and painted over. The latch assembly had operated but the drogue chute spring was insufficiently strong to break the seal. When the sealant was prised away from around the lid, the system operated normally. This error had not been found during a check of the aircraft immediately following repainting. The lid had the appearance of an oblong radio antenna and was not marked in any distinguishing manner. The problem should also have been noticed during a subsequent inspection of the drag chute for moisture. The inspection is required every 90 days if the drag chute has not been deployed, and requires the removal of the lid and drogue chute in order to feel the main chute for moisture. The condition of the sealant would indicate that this had not been carried out.

Significant Factors:

The following factors were considered relevant to the development of the accident

1. Inadequate pre-flight planning and preparation by the flight crew. The runway distance required was in excess of the distance available on either runway.
2. Adverse runway and weather conditions - wet surface and downwind component.
3. Improper sealing of drag chute canister.
4. Inadequate maintenance of the drag chute system.
5. Improper operation of wheel brakes.

Reccomendations:

1. It is recommended that where a drag chute is fitted, the Civil Aviation Authority considers requiring some type of appropriate marking be applied to the canister lid to clearly identify its purpose.