NTSB Identification: Unknown

14 CFR Part 91 General Aviation Aircraft: LEAR M23, registration: N801L

FILE DATE LOCATION AIRCRAFT DATA INJURIES FLIGHT PILOT DATA F S M/N PURPOSE

RATED.

NAME OF AIRPORT - WICHITA

TYPE OF ACCIDENT PHASE OF OPERATION STALL: SPIN TAKEOFF: INITIAL CLIMB WHEELS-UP TAKEOFF: ABORTED PROBABLE CAUSE(S)

PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING PILOT IN COMMAND - FAILED TO USE OR INCORRECTLY USED MISC.EQUIPMENT

FACTOR(S)

MISCELLANEOUS ACTS, CONDITIONS - SIMULATED CONDITIONS

FIRE AFTER IMPACT

REMARKS- ATTEMPTED TAKEOFF WITH SPOILERS EXTENDED

Full narrative is not available