

NTSB Identification: Unknown

14 CFR Part 91 General Aviation
Aircraft: BEECH SNB-5, registration: N90280

FILE	DATE	LOCATION	AIRCRAFT DATA		INJURIES	FLIGHT	PILOT DATA		
			F	S	M/N	PURPOSE			

2-1038	64/6/20	FT LAUDERDALE FLA	BEECH SNB-5	CR-	2	0	0	MISCELLANEOUS	COMMERCIAL, AGE 32, 1075
	TIME - 1350	N90280	PX-	0	0	0	FERRY	TOTAL HOURS, UNK/NR IN	
		DAMAGE-DESTROYED	OT-	0	0	0		TYPE, INSTRUMENT RATED.	
NAME OF AIRPORT - BRADLEY									
TYPE OF ACCIDENT									
PHASE OF OPERATION									
ENGINE FAILURE OR MALFUNCTION									
TAKEOFF: INITIAL CLIMB									
STALL: SPIN									
TAKEOFF: INITIAL CLIMB									
PROBABLE CAUSE(S)									
MISCELLANEOUS ACTS,CONDITIONS - FUEL STARVATION									
PILOT IN COMMAND - MISMANAGEMENT OF FUEL									
PERSONNEL - MAINTENANCE,SERVICING,INSPECTION: INADEQUATE INSPECTION OF AIRCRAFT (OWNER-PILOT)									
FACTOR(S)									
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED									
MISCELLANEOUS ACTS,CONDITIONS - MISSING									
MISCELLANEOUS ACTS,CONDITIONS - FAILURE OF TWO OR MORE ENGINES									
FIRE AFTER IMPACT									
REMARKS- FUEL SELECTOR VALVE DECAL WAS MISSING AND PILOT MADE ERRONEOUS DETERMINATION OF VALVE POSITION.									

Full narrative is not available