

NTSB Identification: MKC71AK016

14 CFR Part 135 Nonscheduled operation of LINDNER AVIATI
Aircraft: BEECH E18S, registration: N29W

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT	PILOT DATA	
				F	S	M/N	PURPOSE		
3-1437	70/9/29	KEOKUK,IOWA	BEECH E18S	CR-	0	2	0	COMMERCIAL	COMMERCIAL, FL.INSTR., AGE 27, 4128 TOTAL HOURS, 600 IN TYPE, NOT INSTRUMENT RATED.
	TIME - 0135		N29W	PX-	0	0	0	AIR TAXI-CARGO	
			DAMAGE-DESTROYED	OT-	0	1	0		
NAME OF AIRPORT - KEOKUK MUNI									
DEPARTURE POINT			INTENDED DESTINATION						
KEOKUK,IOWA			DETROIT,MICH						
TYPE OF ACCIDENT				PHASE OF OPERATION					
COLLISION WITH AIRCRAFT: BOTH ON GROUND				TAXI: OTHER					
PROBABLE CAUSE(S)									
PILOT IN COMMAND - STARTED ENGINE WITHOUT PROPER ASSISTANCE/EQUIPMENT									
PILOT IN COMMAND - DIVERTED ATTENTION FROM OPERATION OF AIRCRAFT									
FIRE AFTER IMPACT									
REMARKS- BEECH PLTS PREOCCUPIED IN COCKPIT. NEITHER ACFT WAS CHOCKED FOR ENG START. NO LINE PERSONNEL AVAIL									

Full narrative is not available