NTSB Identification: MIA71AM091

14 CFR Part 135 Nonscheduled operation of COASTAL AIRWAY Aircraft: BEECH E18S, registration: N456T

FILE	DATE	LOCATION	AIRCRAFT DATA					FLIGHT PURPOSE	PILOT DATA	
3-0109	71/4/21 TIME - 172		BEECH E18S N456T DAMAGE-DESTROYED	PX-	7	0	0	COMMERCIAL AIR TAXI-PASSG		
	NAME OF AIRPORT - HARRY S TRUMAN									
	DEPARTURE POINT INTENDED DESTINATION									
		SAN JUAN,PR								
	TYPE OF ACCIDENT				PHASE OF OPERATION					
	ENGINE FAILURE OR MALFUNCTION			TAKEOFF: INITIAL CLIMB						
	COLLIDED WITH: BUILDING(S)				IN FLIGHT: OTHER					
	PROBABLE CAUSE(S)									
	PERSONNEL - MAINTENANCE,SERVICING,INSPECTION: INADEQUATE MAINTENANCE AND INSPECTION									
	POWERPLANT - ENGINE STRUCTURE: PISTON, PISTON RINGS									
	PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES,DIRECTIVES,ETC.									
	MISCELLANEOUS ACTS, CONDITIONS - IMPROPER EMERGENCY PROCEDURES									
	FACTOR(S)									
	POMERPLANT - LUBRICATING SYSTEM: FILTERS, SCREEN									
	MISCELLANEOUS ACTS, CONDITIONS - COLLAPSED									
	COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE FIRE AFTER IMPACT									
	REMARKS- R ENG PISTON TOPS ERODED, PIECES OF RINGS MISSING.R PROP NOT FEA,LDG GR DWN.DRG DSCNT HIT MOTEL.									

Full narrative is not available