

NTSB Identification: FTW72AF007

14 CFR Part 91 General Aviation
 Aircraft: AEROSTAR 601, registration: N7480S

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-1364	71/7/22 TIME - 1305	FORT WORTH, TEX	AEROSTAR 601 N7480S DAMAGE-DESTROYED	CR- 2 0 0 PX- 0 0 0 OT- 0 0 0	MISCELLANEOUS TEST	COMMERCIAL, FL.INSTR., AGE 35, 2000 TOTAL HOURS, 70 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - MEACHAM DEPARTURE POINT FORT WORTH, TEX INTENDED DESTINATION LOCAL TYPE OF ACCIDENT ENGINE FAILURE OR MALFUNCTION PHASE OF OPERATION TAKEOFF: INITIAL CLIMB COLLISION WITH GROUND/WATER: UNCONTROLLED IN FLIGHT: UNCONTROLLED DESCENT PROBABLE CAUSE(S) POWERPLANT - IGNITION SYSTEM: SPARK PLUG PERSONNEL - MAINTENANCE, SERVICING, INSPECTION: INADEQUATE MAINTENANCE AND INSPECTION PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC. PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED FACTOR(S) MISCELLANEOUS ACTS, CONDITIONS - IMPROPER EMERGENCY PROCEDURES SYSTEMS - HYDRAULIC SYSTEM: OTHER PARTIAL POWER LOSS - PARTIAL LOSS OF POWER - 2 ENGINES REMARKS- ENGS MISFIRED, FOULED PLUGS. PLT FEATH R ENG, GOT BELOW VMC, LOST CTL.HYD PUMP ON R ENG. GR NOT RETRACT						

Full narrative is not available