NTSB Identification: MIA74DKT76

14 CFR Part 135 Nonscheduled operation of LEASE ADVENTUR Aircraft: CESSNA 207, registration: N1504U

FILE	DATE	LOCATION	AIRCRAFT DATA		URIE		FLIGHT PURPOSE	PILOT DATA	
3-1498	TIME - 17	08 IRPORT - OPA LOCKA	CESSNA 207 N1504U DAMAGE-DESTROYED	PX-	0 0	6	COMMERCIAL AIR TAXI-PASSG	COMMERCIAL, AGE 23, 217 TOTAL HOURS, 1 IN TYPE, INSTRUMENT RATED.	
	OPA LOCKA, FLA FREEPORT, BAHAMAS								
	TYPE OF ACCIDENT				PHASE OF OPERATION				
	PROPELLER/ROTOR FAILURE: PROPELLER				TAKEOFF: INITIAL CLIMB				
	GEAR COLLAPSED				LANDING: ROLL				
	PROBABLE CAUSE(S)								
	PILOT IN COMMAND - ATTEMPTED OPERATION W/KNOWN DEFICIENCIES IN EQUIPMENT POWERPLANT - PROPELLER AND ACCESSORIES: HYDRAULIC PITCH CONTROL MECHANISM MISCELLANEOUS ACTS,CONDITIONS - RPM-UNCONTROLLABLE-OVERSPEED PILOT IN COMMAND - IMPROPER LEVEL OFF PILOT IN COMMAND - IMPROPER RECOVERY FROM BOUNCED LANDING								
	FACTOR(S)								
	MISCELLANEOUS ACTS,CONDITIONS - OVERLOAD FAILURE								
	EMERGENCY CIRCUMSTANCES - FORCED LANDING ON AIRPORT/SEAPLANE BASE/HELIPT. SUSPECTED MECHANICAL DISCREPANCY								
	FIRE AFTER IMPACT								
	REMARKS- PROP WOULD NOT RESPOND TO CTL.PLT AWARE OF PROBLEM BFR TKOF.FIRE START							R BRAKE.	

Full narrative is not available