NTSB Identification: IAD78FA048

14 CFR Part 91 General Aviation Aircraft: AERO COMDR 681, registration: N5NP

FILE	DATE	LOCATION	AIRCRAFT DATA			FLIGHT PURPOSE	PILOT DATA		
3-3354	TYPE OF ACCIDENT ENGINE FAILURE OR MALFU		N5NP DAMAGE-DESTROYED INTENDED DESTINATION HUNTINGTON,WV	PX- 1 OT- 0	0 0 0 0 LAST EI MANCI PHASE (LANI	CORP/EXEC NROUTE STOP HESTER,IA DF OPERATION DING: FINAL APPROACH	COMMERCIAL, AGE 62, 9154 TOTAL HOURS, 1395 IN TYPE, INSTRUMENT RATED.		
	PROBABLE CAUSE(S) POWERPLANT - MISCELLANEOUS: POWERPLANT FAILURE FOR UNDETERMINED REASONS PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC. MISCELLANEOUS ACTS, CONDITIONS - IMPROPER EMERGENCY PROCEDURES FACTOR(S) WEATHER - LOW CEILING WEATHER - FOG WEATHER - ICING CONDITIONS-INCLUDES SLEET, FREEZING RAIN, ETC.								
	PARTIAL POWER LOSS - PARTIAL LOSS OF POWER - 1 ENGINE WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, BY RADIO WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT EMERGENCY CIRCUMSTANCES - FORECD LANDING OFF AIRPORT ON LAND								
	SKY CONDITION OBSCURATION VISIBILITY AT ACCIDENT SITE 1/2 MILE OR LESS OBSTRUCTIONS TO VISION AT ACCIDENT SITE FOG WIND DIRECTION-DEGREES 90 TYPE OF WEATHER CONDITIONS BELOW MINIMUMS				CEILING AT ACCIDENT SITE 200 PRECIPITATION AT ACCIDENT SITE DRIZZLE TEMPERATURE-F 33 WIND VELOCITY-KNOTS 5 TYPE OF FLIGHT PLAN IFR				

Full narrative is not available