## NTSB Identification: NYC77FA082

14 CFR Part 135 Scheduled operation of FLIGHT EXPRESS Aircraft: BEECH G18S, registration: N75FA

FILE	DATE LOCATIO	N AIRCRAFT DATA					FLIGHT PURPOSE	PILOT DATA		
3-3318		PA BEECH G18S								
	TIME - 0541						COMMUTER AIR CARRIER AIR TAXI-CARGO S-D	, ,		
	NAME OF AIRPORT - GREAT PITTSBURGH									
	DEPARTURE POINT	INTENDED DESTINATION								
	PITTSBURGH,PA CLEVELAND,OH									
	TYPE OF ACCIDENT			PHASE OF OPERATION						
	ENGINE FAILURE OR MALFUNCTION			TAKEOFF: INITIAL CLIMB						
	STALL: MUSH				IN FLIGHT: OTHER					
	PROBABLE CAUSE(S)  POWERPLANT - FUEL SYSTEM: CARBURETOR									
	MISCELLANEOUS ACTS, CONDITIONS - IMPROPERLY INSTALLED									
	MISCELLANEOUS ACTS, CONDITIONS - LEAK/LEAKAGE									
	PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC.									
	PILOT IN COMMAND - IMPROPER OPERATION OF POWERPLANT & PÓWERPLANT CÓNTROLS									
	FACTOR(S)									
	PILOT IN COMMAND - ATTEMPTED OPERATION W/KNOWN DEFICIENCIES IN EQUIPMENT									
	COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE									
	EMERGENCY CIRCUMSTANCES - FORCED LANDING ON AIRPORT/SEAPLANE BASE/HELIPT.  FIRE AFTER IMPACT									
	REMARKS- RIGHT ENG NOT FEATHERED.TURNED ACFT TOWARD DEAD ENG WHILE RETURNING TO AIRPORT.							•		

Full narrative is not available