NTSB Identification: CHI78FA064

14 CFR Part 135 Nonscheduled Aircraft: PIPER PA-31, registration: N26AN

FILE	DATE	LOCATION	AIRCRAFT DATA					FLIGHT PURPOSE	PILOT DATA	
3-4341	NAME OF		DAMAGE-DESTROYED	PX-	5	0	0	COMMERCIAL AIR TAXI-PASSG		
	SAVOY,IL		CLEVELAND, OH							
	TYPE OF ACCIDENT			PHASE OF OPERATION						
	ENGINE FAILURE OR MALFUNCTION				TAKEOFF: INITIAL CLIMB					
	STALL: SPIRAL			TAKEOFF: INITIAL CLIMB						
	PROBABLE CAUSE(S)									
	POWERPLANT - ENGINE STRUCTURE: MASTER AND CONNECTING RODS									
	MISCELLANEOUS ACTS,CONDITIONS - MATERIAL FAILURE									
	PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING									
	MISCELLANEOUS ACTS, CONDITIONS - IMPROPER EMERGENCY PROCEDURES									
	PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED									
	FACTOR(S)									
	PERSONNEL - MISCELLANEOUS-PERSONNEL: OTHER									
	COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE									
	EMERGENCY CIRCUMSTANCES - FORCED LANDING ON AIRPORT/SEAPLANE BASE/HELIPT.									
	REMARKS- CONNECTING ROD BOLT OR NUT FAILURE FOR UNDETERMINED REASONS.PLTS FAA CHECK FLT NOT COMPLETE.									
	Full powerfive to not everible to									

Full narrative is not available