NTSB Identification: FTW82AA016

14 CFR Part 91 General Aviation Aircraft: BEECH E90, registration: N114K

FILE	DATE	LOCATION	AIRCRAFT DATA	IN		RIES S M		FLIGHT PURPOSE	PILOT DATA	
3-3645	81/10/26 TIME - 14	MINERAL WELLS,TX 31	BEECH E90 N114K DAMAGE-DESTROYED	CR- PX- OT-	0	0	0		ATP,FLIGHT INSTR., AGE 43, 8500 TOTAL HOURS, 1500 IN TYPE, INSTRUMENT RATED.	
	NAME OF AIRPORT - MINERAL WELLS DEPARTURE POINT INTENDED DESTINATION MINERAL WELLS,TX SHREVEPORT,LA TYPE OF ACCIDENT AIRFRAME FAILURE: IN FLIGHT				PHASE OF OPERATION TAKEOFF: INITIAL CLIMB					
	PROBABLE CAUSE(S) PERSONNEL - PRODUCTION-DESIGN-PERSONNEL: POOR/INADEQUATE DESIGN PERSONNEL - PRODUCTION-DESIGN-PERSONNEL: OTHER PERSONNEL - RULES, REGULATIONS, STANDARDS PERSONNEL AIRFRAME - WINGS: WING ATTACHMENT FITTINGS, BOLTS MISCELLANEOUS ACTS, CONDITIONS - FATIGUE FRACTURE MISCELLANEOUS ACTS, CONDITIONS - CORRODED/CORROSION									
	FACTOR(S) MISCELLANEOUS ACTS,CONDITIONS - SEPARATION IN FLIGHT FIRE AFTER IMPACT REMARKS- PRE INTRGRNLR STRS COR CRKG FD ON L WG LWR ATHMT BOLT. LACK OF CO OR FAA REQMT FOR ADQ INSP PROCS.									

Full narrative is not available