

NTSB Identification: NYC77FNE34

14 CFR Part 91 General Aviation
Aircraft: NOORDUYN UC64A, registration: N69795

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-3306	77/8/28	NEW SALEM,MA	NOORDUYN UC64A	CR-	0	0	1	MISCELLANEOUS
	TIME - 1200		N69795	PX-	0	0	9	PARAJUMP-SPORT
			DAMAGE-DESTROYED	OT-	0	0	0	COMMERCIAL, FL.INSTR., AGE 21, 859 TOTAL HOURS, 125 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - ORANGE MUNI								
DEPARTURE POINT			INTENDED DESTINATION					
NEW SALEM,MA			LOCAL					
TYPE OF ACCIDENT				PHASE OF OPERATION				
ENGINE FAILURE OR MALFUNCTION				IN FLIGHT: CLIMB TO CRUISE				
COLLIDED WITH: TREES				LANDING: FINAL APPROACH				
PROBABLE CAUSE(S)								
POWERPLANT - FUEL SYSTEM: CARBURETOR								
MISCELLANEOUS ACTS,CONDITIONS - CORRODED/CORROSION								
MISCELLANEOUS ACTS,CONDITIONS - OBSTRUCTED								
MISCELLANEOUS ACTS,CONDITIONS - FUEL STARVATION								
FACTOR(S)								
TERRAIN - HIGH OBSTRUCTIONS								
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE								
EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND								
FIRE AFTER IMPACT								
REMARKS- CORROSION DEPOSIT FOUND BLOCKING ACCELERATOR PUMP OUTLET ORIFICE OF BENDIX STROMBERG NA-Y9E1 CARB.								

Full narrative is not available