

DUTY ON WHICH ENGAGED:  Solo flying practice.	COURT OF INQUIRY, INVESTIGATING OFFICER  OR COMMANDING OFFICER'S REPORT:
) NATURE OF ACCIDENT AND STAGE OF FLIGHT: ) Aircraft was seen by witnessess	DATE: 7-6-42. INVESTIGATING OFFICER'S REPORT ) COMPOSITION: // Ca/F > 6-42.
flying down the South Saskatchewan River at a low altitude. After rounding a curve in the river the	F/L E.W.C. Sharpe, C2797 No.2 T.C. Headquarters.
) aircraft struck a ferry cable caus- ing a wing to be sheared off. A/C ) was a total wreck.  PRIMARY CAUSE:  Deliberate unautherized low flying.	RECOMMENDATIONS:  Installation of recording baragraphs in some aircraft unknown to crews, Low flying orders are continually brought to the attention of all flying personnel.
22. COLLISIONS OBSTR.	Recommendations not concurred in by A.O.C.  ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  Nil.  Conclusions of A.I.B. Deliberate unauthorized low flying.
) SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
) Aircraft struck a Ferry Gable.	RECORDED BY DATE
, 	CHECKED BY DATE