## NTSB Identification: Unknown

14 CFR Part 91 General Aviation

Aircraft: BEECHCRAFT H18S, registration: N517DC

FILE DATE LOCATION AIRCRAFT DATA INJURIES FLIGHT PILOT DATA F S M/N PURPOSE

NAME OF AIRPORT - LUNKEN

TYPE OF ACCIDENT PHASE OF OPERATION

ENGINE FAILURE OR MALFUNCTION TAKEOFF: INITIAL CLIMB

TAKEOFF: INITIAL CLIMB STALL

PROBABLE CAUSE(S)

POWERPLANT - IGNITION SYSTEM: SPARK PLUG

MISCELLANEOUS ACTS, CONDITIONS - IMPROPER EMERGENCY PROCEDURES

COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE

EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND

REMARKS- IMPROPER SINGLE ENGINE FLT PROCEDURES

Full narrative is not available

PRIVATE, AGE 46, 4016