NTSB Identification: MIA66F0084

14 CFR Part 91 General Aviation Aircraft: BEECH C-18S, registration: N7871B

FILE DATE LOCATION AIRCRAFT DATA INJURIES FLIGHT PILOT DATA F S M/N PURPOSE

ME - 0500 N/8/TB PX- 0 0 0 ASSOC CROP CIL ACTIVITY 61, 12800 TOTAL HOURS

DAMAGE-DESTROYED OT- 0 0 0 900 IN TYPE, INSTRUMENT

DATE

NAME OF AIRPORT - MARATHON

TYPE OF ACCIDENT PHASE OF OPERATION

ENGINE FAILURE OR MALFUNCTION TAKEOFF: INITIAL CLIMB DITCHING LANDING: LEVEL OFF/TOUCHDOWN

PROBABLE CAUSE(S)

MISCELLANEOUS ACTS.CONDITIONS - FUEL STARVATION

PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING

MISCELLANEOUS ACTS, CONDITIONS - FUEL SELECTOR POSITIONED BETWEEN TANKS

EACTOR(S)

MISCELLANEOUS ACTS.CONDITIONS - AIRCRAFT CAME TO REST IN WATER

COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES

EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON WATER

SPECIAL DATA

TOTAL HOURS IN CROP CONTROL - 7000 KIND OF OPERATION - SPRAYING TOWNS

KIND OF CROP - MOSQUITO CONTROL TYPE OF CHEMICAL USED - LIQUID CHEMICAL-NONTOXIC

PILOT'S SEAT BELT -FASTENED-PROPERLY

GLOVES - NOT USED

GOGGLES - NOT USED CRASH HELMET - AVAILABLE-NOT USED COCKPIT CRASHPAD - NOT INSTALLED CRASH BAR - NOT INSTALLED TANK/HOPPER-LOCATION - AFT OF PILOT TERRAIN-TYPE - LEVEL, FLAT

ELEVATION-AREA BEING TREATED-FEET - 9

Full narrative is not available