NTSB Identification: ANC69A0021

14 CFR Part 135 Nonscheduled operation of MUNZ NORTHERN Aircraft: AERO COMDR 680, registration: N401M

FILE	DATE LOCATION		AIRCRAFT DATA	INJURIES F S M/N				PILOT DATA			
3-4735	TIME - 111	TIN CITY,ALAS 10 ERPORT - TIN CITY	AERO COMDR 680 N401M DAMAGE-SUBSTANTIAL	PX-	0	1	0	COMMERCIAL AIR TAXI-PASSG	COMMERCIAL, AGE 34, 5219 TOTAL HOURS, 1897 IN TYPE, INSTRUMENT RATED.		
	TYPE OF AC	TYPE OF ACCIDENT			PHASE OF OPERATION						
	ENGINE FAILURE OR MALFUNCTION STALL					TAKEOFF: RUN TAKEOFF: INITIAL CLIMB					
	PROBABLE CAUSE(S)										
	POWERPLANT - IGNITION SYSTEM: SPARK PLUG MISCELLANEOUS ACTS,CONDITIONS - CARBON DEPOSITS										
	PILOT IN COMMAND - ATTEMPTED OPERATION W/KNOWN DEFICIENCIES IN EQUIPMENT										
	PILOT IN COMMAND - FAILED TO ABORT TAKEOFF PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED PARTIAL POWER LOSS - PARTIAL LOSS OF POWER - 1 ENGINE REMARKS- WITNESSES STATED RT ENG BACKFIRED.PLT CONT T/O,CLIMBED AT STEEP ATTITUDE.2 PREVIOUS T/O ABORTED.										

Full narrative is not available