NTSB Identification: NYC70AN103

14 CFR Part 135 Scheduled operation of COMMUTER AIRL* Aircraft: BEECH C-45H, registration: N497DM

FILE	DATE	LOCATION	AIRCRAFT DATA					FLIGHT PURPOSE	PILOT DATA	
3-0021	70/3/22 TIME - 10		BEECH C-45H N497DM DAMAGE-DESTROYED	PX-	2	7	0	COMMUTER AIR CARRIER	AIRLINE TRANSPORT, AGE 42, 6630 TOTAL HOURS, 106 IN TYPE, INSTRUMENT RATED.	
	NAME OF AIRPORT - BROOME COUNTY									
	DEPARTURE POINT INTENDED DESTINATION									
	BINGHAMTON, NY		WASHINGTON, DC							
	TYPE OF ACCIDENT							F OPERATION		
	STALL: MUSH				TAKEOFF: INITIAL CLIMB TAKEOFF: ABORTED					
	WHEELS-UP PROBABLE CAUSE(S)					1.	AKE	DFF: ABURTED		
	PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING									
	MISCELLANEOUS ACTS, CONDITIONS - AIRFRAME ICE									
	WEATHER - ICING CONDITIONS-INCLUDES SLEET, FREEZING RAIN, ETC.									
	PILOT IN COMMAND - DELAYED ACTION IN ABORTING TAKEOFF									
	MISCELLANEOUS ACTS,CONDITIONS - INTENTIONAL WHEELS-UP									
	FACTOR(S)									
	WEATHER - LOW CEILING									
	WEATHER - SNOW									
	WEATHER BRIEFING - BRIEFED BY WEATHER BUREAU PERSONNEL, IN PERSON WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT									
	SKY COND		SUBSTANTIALLY CORRECT		_	СТІ	TNG	AT ACCIDENT SITE		
	OBSCURATION				300					
	VISIBILITY AT ACCIDENT SITE				PRECIPITATION AT ACCIDENT SITE					
	1/2 MILE OR LESS				SNOW					
	OBSTRUCTIONS TO VISION AT ACCIDENT SITE				RELATIVE BEARING OF WIND					
	NONE				LEFT QUARTERING HEAD WIND 293-337 DEGREES					
	TEMPERATURE-F				WIND DIRECTION-DEGREES					
	34				100					
	WIND VELOCITY-KNOTS				TYPE OF WEATHER CONDITIONS					
	10 IFR TYPE OF FLIGHT PLAN									
		FLIGHT PLAN								
	IFR									

Full narrative is not available