

NTSB Identification: MIA72AM001

14 CFR Part 91 General Aviation
Aircraft: DASSAULT FALCON, registration: N805F

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | | FLIGHT PURPOSE | PILOT DATA |
|--------|--|----------------|----------------------|-------------------------|---|-----|----------------|---------------|
| | | | | F | S | M/N | | |
| 3-1996 | 71/7/5 | BOCA RATON,FLA | DASSAULT FALCON | CR- | 0 | 2 | 0 | NONCOMMERCIAL |
| | TIME - 1245 | | N805F | PX- | 0 | 0 | 0 | CORP/EXEC |
| | | | DAMAGE-DESTROYED | OT- | 0 | 0 | 0 | |
| | NAME OF AIRPORT - BOCA RATON | | | | | | | |
| | DEPARTURE POINT | | INTENDED DESTINATION | | | | | |
| | WHITE PLAINS,NY | | BOCA RATON,FLA | | | | | |
| | TYPE OF ACCIDENT | | | PHASE OF OPERATION | | | | |
| | ENGINE FAILURE OR MALFUNCTION | | | LANDING: FINAL APPROACH | | | | |
| | COLLIDED WITH: DIRT BANK | | | LANDING: ROLL | | | | |
| | PROBABLE CAUSE(S) | | | | | | | |
| | PILOT IN COMMAND - IMPROPER OPERATION OF POWERPLANT & POWERPLANT CONTROLS | | | | | | | |
| | AIRPORTS/AIRWAYS/FACILITIES - AIRPORT CONDITIONS: OTHER | | | | | | | |
| | MISCELLANEOUS ACTS,CONDITIONS - LANDED IN CONSTRUCTION AREA | | | | | | | |
| | FACTOR(S) | | | | | | | |
| | MISCELLANEOUS ACTS,CONDITIONS - FAILURE OF TWO OR MORE ENGINES | | | | | | | |
| | COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE | | | | | | | |
| | EMERGENCY CIRCUMSTANCES - FORCED LANDING ON AIRPORT/SEAPLANE BASE/HELIP.T. | | | | | | | |
| | REMARKS- RETARDED THRUST LEVERS AFT,INADVERTENTLY SHUT DOWN BOTH ENGS. | | | | | | | |

Full narrative is not available