

NTSB Identification: MKC73AK040

14 CFR Part 135 Scheduled operation of LUTHI AVIATION
 Aircraft: BEECH C-45H, registration: N717B

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-3615	72/11/29 TIME - 2027	ST.PAUL,MINN	BEECH C-45H N717B DAMAGE-DESTROYED	CR- 1 0 0 PX- 1 0 0 OT- 0 0 0	COMMERCIAL COMMUTER AIR CARRIER AIR TAXI-CARGO S-D	COMMERCIAL, AGE 25, 1324 TOTAL HOURS, 408 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - MINN.ST.PAUL INTL						
DEPARTURE POINT		INTENDED DESTINATION		LAST ENROUTE STOP		
MINNEAPOLIS,MINN		ST.PAUL,MINN		DULUTH,MINN		
TYPE OF ACCIDENT				PHASE OF OPERATION		
ENGINE FAILURE OR MALFUNCTION				LANDING: FINAL APPROACH		
COLLIDED WITH: TREES				LANDING: FINAL APPROACH		
PROBABLE CAUSE(S)						
PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING						
PILOT IN COMMAND - MISMANAGEMENT OF FUEL						
MISCELLANEOUS ACTS,CONDITIONS - FUEL EXHAUSTION						
TERRAIN - HIGH OBSTRUCTIONS						
FACTOR(S)						
MISCELLANEOUS ACTS,CONDITIONS - FAILURE OF TWO OR MORE ENGINES						
MISCELLANEOUS ACTS,CONDITIONS - PILOT FATIGUE						
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES						
EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND						
FIRE AFTER IMPACT						
REMARKS- DIDNT REFUEL AT DULUTH.RAN OUT OF FUEL,HIT TREE THEN 2 HOUSES.						

Full narrative is not available