

NTSB Identification: CHI73AC021

14 CFR Part 135 Scheduled operation of ISLAND AIRLIN*
Aircraft: FORD MTR CO 4-AT-B, registration: N7684

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA	
				F	S	M/N			
3-3419	72/8/21	PORT CLINTON,OHIO	FORD MTR CO 4-AT-B	CR-	0	0	1	COMMERCIAL	COMMERCIAL, AGE 33, 5078
	TIME - 0945		N7684	PX-	0	1	14	COMMUTER AIR CARRIER	TOTAL HOURS, 2637 IN
			DAMAGE-DESTROYED	OT-	0	0	0	AIR TAXI-PASSG S-D	TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - PORT CLINTON									
DEPARTURE POINT		INTENDED DESTINATION							
PORT CLINTON,OHIO		PUT-IN-BAY,OHIO							
TYPE OF ACCIDENT				PHASE OF OPERATION					
ENGINE FAILURE OR MALFUNCTION				TAKEOFF: INITIAL CLIMB					
STALL				LANDING: TRAFFIC PATTERN-CIRCLING					
PROBABLE CAUSE(S)									
POWERPLANT - ENGINE CONTROLS: MIXTURE CONTROL ASSEMBLIES									
MISCELLANEOUS ACTS,CONDITIONS - IMPROPERLY SECURED									
MISCELLANEOUS ACTS,CONDITIONS - IMPROPERLY INSTALLED									
PERSONNEL - MAINTENANCE,SERVICING,INSPECTION: INADEQUATE MAINTENANCE AND INSPECTION									
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED									
PARTIAL POWER LOSS - PARTIAL LOSS OF POWER - 1 ENGINE									
REMARKS- R ENG LOST PWR. SAFETY WIRE FAILED,ALLOWED MIXT CTL TO MOVE FROM RICH POS.WIRE IN POOR COND.									

Full narrative is not available