

NTSB Identification: FTW73AF071

14 CFR Part 135 Scheduled operation of SMB STAGE LINE
 Aircraft: BEECH E18S, registration: N73JB

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-1050	73/5/31 TIME - 0200	TYLER, TEX	BEECH E18S N73JB DAMAGE-DESTROYED	CR- PX- OT-	1 0 0	0 0 0	COMMERCIAL COMMUTER AIR CARRIER AIR TAXI-CARGO S-D	AIRLINE TRANSPORT, AGE 38, 5600 TOTAL HOURS, 2600 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - POUNDS		DEPARTURE POINT		INTENDED DESTINATION		LAST ENROUTE STOP		
DALLAS, TEX		DALLAS, TEX		LONGVIEW, TEX		TYLER, TEX		
TYPE OF ACCIDENT		UNDERSHOOT		COLLIDED WITH: TREES		PHASE OF OPERATION		
PROBABLE CAUSE(S)		PILOT IN COMMAND - MISJUDGED DISTANCE AND ALTITUDE		TERRAIN - HIGH OBSTRUCTIONS		LANDING: FINAL APPROACH		
FACTOR(S)		MISCELLANEOUS ACTS, CONDITIONS - PILOT FATIGUE		FIRE AFTER IMPACT		LANDING: FINAL APPROACH		
REMARKS- HIT TREES 32 FT AGL 1 3/4 MI FROM ARPT. PLT HAD LDG LTS ON, GR DOWN.								

Full narrative is not available