

# NTSB Identification: FTW74AF047

14 CFR Part 135 Scheduled operation of TRICON AIRLIN\*  
 Aircraft: BEECH C-45H, registration: N118X

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-3717	73/12/26	DALLAS,TEX	BEECH C-45H N118X DAMAGE-DESTROYED	CR- 1	0	0	COMMERCIAL COMMUTER AIR CARRIER AIR TAXI-CARGO S-D	AIRLINE TRANSPORT, AGE 29, 2050 TOTAL HOURS, 165 IN TYPE, INSTRUMENT RATED.
		NAME OF AIRPORT - LOVE FIELD						
		DEPARTURE POINT DALLAS, TEX	INTENDED DESTINATION BEAUMONT, TEX					
		TYPE OF ACCIDENT STALL: SPIN			PHASE OF OPERATION LANDING: TRAFFIC PATTERN-CIRCLING			
		PROBABLE CAUSE(S) PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING MISCELLANEOUS ACTS,CONDITIONS - IMPROPERLY LOADED AIRCRAFT-WEIGHT-AND/OR C.G.						
		EMERGENCY CIRCUMSTANCES - PRECAUTIONARY LANDING ON AIRPORT SUSPECTED MECHANICAL DISCREPANCY						
		FIRE AFTER IMPACT						
		REMARKS- PLT RPRTD AFTR TKOF UN RAISE GR,REENTERED DWNWND,TURNED FNL.CG 8.9IN AFT REAR LMT.HIT HOUSES.						

Full narrative is not available