

# NTSB Identification: NYC74AN051

14 CFR Part 135 Nonscheduled operation of MOREY L.WYMAN  
Aircraft: BEECH E18S, registration: N387B

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-3716	73/12/7	CORAPOLIS,PA	BEECH E18S	CR-	2	0 0	COMMERCIAL	COMMERCIAL, FL.INSTR.,
	TIME - 0333		N387B	PX-	0	0 0	AIR TAXI-CARGO	AGE 57, 13600 TOTAL
			DAMAGE-DESTROYED	OT-	0	0 0		HOURS, 3700 IN TYPE,
				INSTRUMENT RATED.				
NAME OF AIRPORT - GREATER PITTSBURG								
DEPARTURE POINT			INTENDED DESTINATION					
CORAPOLIS,PA			PONTIAC,MICH					
TYPE OF ACCIDENT				PHASE OF OPERATION				
STALL				TAKEOFF: INITIAL CLIMB				
PROBABLE CAUSE(S)								
PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING								
PILOT IN COMMAND - MISUSED OR FAILED TO USE FLAPS								
PILOT IN COMMAND - FAILED TO ABORT TAKEOFF								
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED								
FACTOR(S)								
MISCELLANEOUS ACTS,CONDITIONS - FAILED TO USE ALL AVAILABLE RUNWAY								
PILOT IN COMMAND - FAILED TO RETRACT LANDING GEAR								
FIRE AFTER IMPACT								
REMARKS- INTERSECTION TKOF-4400FT REMAINING.FLAPS FULL DN								

Full narrative is not available