

# NTSB Identification: CHI75AC004

14 CFR Part 135 Nonscheduled operation of WYMAN PILOT SE  
Aircraft: BEECH D18S, registration: N193CP

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA	
				F	S	M/N			
3-1848	74/7/9 TIME - 2056	HILLSBORO,OHIO	BEECH D18S	CR-	0	0	1	COMMERCIAL	AIRLINE TRANSPORT, AGE 60, 10500 TOTAL HOURS, 3500 IN TYPE, INSTRUMENT RATED.
			N193CP	PX-	0	0	0	AIR TAXI-CARGO	
			DAMAGE-DESTROYED	OT-	0	0	0		
	NAME OF AIRPORT - HIGHLAND CO								
	DEPARTURE POINT		INTENDED DESTINATION						
	HILLSBORO,OHIO		PONTIAC,MICH						
	TYPE OF ACCIDENT				PHASE OF OPERATION				
	ENGINE FAILURE OR MALFUNCTION				TAKEOFF: RUN				
	COLLIDED WITH: TREES				TAKEOFF: ABORTED				
	PROBABLE CAUSE(S)								
	PERSONNEL - MAINTENANCE,SERVICING,INSPECTION: INADEQUATE MAINTENANCE AND INSPECTION								
	POWERPLANT - IGNITION SYSTEM: MAGNETOS								
	MISCELLANEOUS ACTS,CONDITIONS - IMPROPER ALIGNMENT/ADJUSTMENT								
PILOT IN COMMAND - DELAYED ACTION IN ABORTING TAKEOFF									
PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS									
FACTOR(S)									
TERRAIN - ROUGH/UNEVEN									
TERRAIN - HIGH OBSTRUCTIONS									
PARTIAL POWER LOSS - PARTIAL LOSS OF POWER - 1 ENGINE									
FIRE AFTER IMPACT									
REMARKS- BECAME AIRBORNE DRG ABORT.									

Full narrative is not available