## NTSB Identification: CHI77FA055

14 CFR Part 91 General Aviation Aircraft: FORD 4-AT-B, registration: N7584

FILE			AIRCRAFT DATA							PILOT DATA	
3-4245		PUT-IN-BAY,OH	FORD 4-AT-B	CR- PX-	0 0	1 0	9 2	COMMERCIAL			
	NAME OF A	\IRPORT - PUT-IN-BA\		01-	U	O	0			INSTROMENT RATED:	
	DEPARTURE POINT INTENDED DESTINATION										
		·BAY,OH									
	TYPE OF ACCIDENT		TORT CELITION, OIL	PHASE OF OPERATION							
	ENGINE FAILURE OR MALFUNCTION			TAKEOFF: INITIAL CLIMB							
	COLLIDED WITH: WIRES/POLES				LANDING: TRAFFIC PATTERN-CIRCLING						
	PROBABLE CAUSE(S)										
	PILOT IN COMMAND - MISMANAGEMENT OF FUEL										
	MISCELLANEOUS ACTS,CONDITIONS - FUEL SELECTOR POSITIONED BETWEEN TANKS										
	MISCELLANEOUS ACTS, CONDITIONS - FUEL STARVATION										
	FACTOR(S)										
	MISCELLANEOUS ACTS,CONDITIONS - FAILURE OF TWO OR MORE ENGINES WEATHER - UNFAVORABLE WIND CONDITIONS										
	COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES										
	EMERGENCY CIRCUMSTANCES - FORCED LANDING ON AIRPORT/SEAPLANE BASE/HELIPT.										
	SKY CONDITION			CEILING AT ACCIDENT SITE							
	SCATTERED			UNLIMITED							
	VISIBILITY AT ACCIDENT SITE				PRECIPITATION AT ACCIDENT SITE						
	5 OR OVER(UNLIMITED)			NONE							
	OBSTRUCTIONS TO VISION AT ACCIDENT SITE NONE				RELATIVE BEARING OF WIND RIGHT CROSS WIND 068-112 DEGREES						
	WIND DIRECTION-DEGREES 240				WIND VELOCITY-KNOTS 35						
		WEATHER CONDITIONS			T۷			FLIGHT PLAN			
		EATHER CONDITIONS				-		LIGHT LEAN			
	VFR					NON	-				

Full narrative is not available