

# NTSB Identification: MIA77FA026

14 CFR Part 91 General Aviation  
 Aircraft: CESSNA 411, registration: N99JM

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-3847	77/1/25 TIME - 1315	FT MYERS,FL	CESSNA 411 N99JM DAMAGE-DESTROYED	CR- 2 0 0 PX- 0 0 0 OT- 0 0 0	INSTRUCTIONAL DUAL	COMMERCIAL, FL.INSTR., AGE 43, 6022 TOTAL HOURS, 10 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - FT MYERS MUNI DEPARTURE POINT FT MYERS,FL INTENDED DESTINATION LOCAL TYPE OF ACCIDENT STALL PHASE OF OPERATION LANDING: FINAL APPROACH PROBABLE CAUSE(S) DUAL STUDENT - FAILED TO OBTAIN/MAINTAIN FLYING SPEED PILOT IN COMMAND - INADEQUATE SUPERVISION OF FLIGHT FACTOR(S) MISCELLANEOUS ACTS,CONDITIONS - SIMULATED CONDITIONS WEATHER - UNFAVORABLE WIND CONDITIONS SKY CONDITION SCATTERED CEILING AT ACCIDENT SITE UNLIMITED VISIBILITY AT ACCIDENT SITE 5 OR OVER(UNLIMITED) PRECIPITATION AT ACCIDENT SITE NONE OBSTRUCTIONS TO VISION AT ACCIDENT SITE NONE TEMPERATURE-F 64 WIND DIRECTION-DEGREES 300 WIND VELOCITY-KNOTS 18 TYPE OF WEATHER CONDITIONS VFR TYPE OF FLIGHT PLAN NONE FIRE AFTER IMPACT REMARKS- ACCD OCCURRED DURING SIMULATED SINGLE ENG APPROACH IN STEEP TURN CLOSE IN TO RUNWAY.GUSTS TO 25KTS						

Full narrative is not available