

NTSB Identification: MIA78DA033

14 CFR Part 91 General Aviation
 Aircraft: BEECH B90, registration: N55MG

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-3619	77/11/26 TIME - 1705	NR.CHARLESTON,SC	BEECH B90 N55MG DAMAGE-DESTROYED	CR- 0 0 1 PX- 0 0 1 OT- 0 0 0	NONCOMMERCIAL PLEASURE/PERSONAL TRANSP	AIRLINE TRANSPORT, AGE 44, 6630 TOTAL HOURS, 175 IN TYPE, INSTRUMENT RATED.
DEPARTURE POINT		INTENDED DESTINATION				
SOUTH CAICOS,BWI		WILMINGTON,DE				
TYPE OF ACCIDENT				PHASE OF OPERATION		
ENGINE FAILURE OR MALFUNCTION				IN FLIGHT: NORMAL CRUISE		
DITCHING				LANDING: LEVEL OFF/TOUCHDOWN		
PROBABLE CAUSE(S)						
PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING						
PILOT IN COMMAND - ATTEMPTED OPERATION W/KNOWN DEFICIENCIES IN EQUIPMENT						
PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING						
PILOT IN COMMAND - MISMANAGEMENT OF FUEL						
MISCELLANEOUS ACTS,CONDITIONS - FUEL EXHAUSTION						
FACTOR(S)						
MISCELLANEOUS ACTS,CONDITIONS - MISCALCULATED FUEL CONSUMPTION						
MISCELLANEOUS ACTS,CONDITIONS - FAILURE OF TWO OR MORE ENGINES						
MISCELLANEOUS ACTS,CONDITIONS - AIRCRAFT CAME TO REST IN WATER						
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES						
EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON WATER						

Full narrative is not available