

NTSB Identification: LAX78FA037

14 CFR Part 135 Nonscheduled operation of LAKE HAVASU
 Aircraft: CESSNA T207A, registration: N7354U

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-0991	78/3/22	NR.RIVERSIDE,CA	CESSNA T207A	CR- 1 0 0	COMMERCIAL	COMMERCIAL, AGE 63, 6300
	TIME - 2042		N7354U	PX- 5 0 0	AIR TAXI-PASSG	TOTAL HOURS, 30 IN TYPE,
			DAMAGE-DESTROYED	OT- 0 0 0		INSTRUMENT RATED.
	DEPARTURE POINT	INTENDED DESTINATION				
	SANTA ANA,CA	LAKE HAVASU CITY,AZ				
	TYPE OF ACCIDENT				PHASE OF OPERATION	
	COLLISION WITH GROUND/WATER: CONTROLLED				IN FLIGHT: NORMAL CRUISE	
	PROBABLE CAUSE(S)					
	PILOT IN COMMAND - CONTINUED VFR FLIGHT INTO ADVERSE WEATHER CONDITIONS					
	PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING					
	FACTOR(S)					
	MISCELLANEOUS ACTS,CONDITIONS - UNWARRANTED LOW FLYING					
	WEATHER - LOW CEILING					
	WEATHER - FOG					
	WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, BY PHONE					
	WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT					
	SKY CONDITION				CEILING AT ACCIDENT SITE	
	BROKEN				1200	
	VISIBILITY AT ACCIDENT SITE				PRECIPITATION AT ACCIDENT SITE	
	5 OR OVER(UNLIMITED)				DRIZZLE	
	OBSTRUCTIONS TO VISION AT ACCIDENT SITE				TEMPERATURE-F	
	FOG				54	
	WIND DIRECTION-DEGREES				WIND VELOCITY-KNOTS	
	40				2	
	TYPE OF WEATHER CONDITIONS				TYPE OF FLIGHT PLAN	
	IFR				OTHER	
	REMARKS- VFR FLT PLAN FILED BUT NOT OPENED.					

Full narrative is not available