

NTSB Identification: DEN78FA020

14 CFR Part 91 General Aviation
Aircraft: DEHAVILLAND DHC-6, registration: N982FL

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
1-0013	78/1/18 TIME - 1503	PUEBLO,CO	DEHAVILLAND DHC-6 N982FL DAMAGE-DESTROYED	CR- 2 0 0 PX- 1 0 0 OT- 0 0 0	TRAINING	ATP, FLIGHT INSTR., AGE 48, 15284 TOTAL HOURS, 307 IN TYPE, INSTRUMENT RATED.

NAME OF AIRPORT - PUEBLO MEMORIAL
OPERATOR - FRONTIER AIRLINES, INC.
DEPARTURE POINT INTENDED DESTINATION
PUEBLO,CO LOCAL
TYPE OF ACCIDENT PHASE OF OPERATION
STALL TAKEOFF: INITIAL CLIMB
PROBABLE CAUSE(S)
CHECK PILOT - FAILED TO OBTAIN/MAINTAIN FLYING SPEED
CHECK PILOT - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC.
CHECK PILOT - MISUSED OR FAILED TO USE FLAPS
REMARKS- FLAPS FOUND IN FULLY EXTENDED 30DEG POSITION. FLAP SETTING FOR NORMAL TKOF IS 10DEG.

Full narrative is not available