NTSB Identification: DCA78AA021

14 CFR Part 135 Scheduled operation of ANTILLES AIR B Aircraft: GRUMMAN G-21A, registration: N7777V

FILE	DATE L	OCATION	AIRCRAFT DATA						PILOT DATA
					r	5 I	/ IN	PURPOSE	
3-3128	78/9/2 NR.ST T TIME - 1021	HOMAS,USVI	N7777V	PX-	3	7	0	COMMERCIAL COMMUTER AIR CARRIER AIR TAXI-PASSG S-D	69, 42005 TOTAL HOURS,
	DEPARTURE POINT	IN	ITENDED DESTINATION						
	ST CROIX,USVI		ST THOMAS,USVI						
	TYPE OF ACCIDENT			P	PHAS	E C	F OPERATION		
	ENGINE FAILURE OR MALFUNCTION			IN FLIGHT: NORMAL CRUISE					
	COLLISION WITH GROUND/WATER: CONTROLLED IN FLIGHT: OTHER								
	PROBABLE CAUSE(S)								
	PERSONNEL - MAINTENANCE,SERVICING,INSPECTION: IMPROPER MAINTENANCE (MAINTENANCE PERSONNEL)								
	POWERPLANT - ENGINE STRUCTURE: CYLINDER ASSEMBLY								
	MISCELLANEOUS ACTS, CONDITIONS - FATIGUE FRACTURE								
	PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING MISCELLANEOUS ACTS, CONDITIONS - IMPROPER EMERGENCY PROCEDURES								
	FACTOR(S)								
	PERSONNEL - OPERATIONAL SUPERVISORY PERSONNEL: INADEQUATE SUPERVISION OF FLIGHT CREW								
	PERSONNEL - OPERATIONAL SUPERVISORY PERSONNEL: DEFICIENCY, COMPANY MAINTAINED EOPHT, SERVICES, REGULATION								
	PERSONNEL - RULES, REGULATIONS, STANDARDS PERSONNEL								
	MISCELLANEOUS ACTS, CONDITIONS - AIRCRAFT CAME TO REST IN WATER								
	PARTIAL POWER LOSS - PARTIAL LOSS OF POWER - 1 ENGINE								
	EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON WATER								
	REMARKS- STC APPROVED FLT AT 8750LBS MGW.TEST INDICATE MGW APPROX 8150LBS.								

Full narrative is not available