

NTSB Identification: NYC78FA076

14 CFR Part 135 Nonscheduled operation of MONTAUK CARIBE
 Aircraft: PIPER PA-31, registration: N9093Y

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | PILOT DATA |
|--|-----------------------|------------------|---|-------------------------------------|------------------------------|--|
| 3-3499 | 78/8/7 TIME - 0033 | EAST HAMPTON, NY | PIPER PA-31 N9093Y DAMAGE-SUBSTANTIAL | CR- 0 0 2 PX- 0 0 0 OT- 0 0 0 | COMMERCIAL AIR TAXI-PASSG | AIRLINE TRANSPORT, AGE 41, 2507 TOTAL HOURS, 150 IN TYPE, INSTRUMENT RATED. |
| NAME OF AIRPORT - EAST HAMPTON DEPARTURE POINT INTENDED DESTINATION ELMIRA, NY EAST HAMPTON, NY TYPE OF ACCIDENT PHASE OF OPERATION STALL LANDING: MISSED APPROACH PROBABLE CAUSE(S) PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED FACTOR(S) WEATHER - FOG WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, BY PHONE WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT SKY CONDITION CEILING AT ACCIDENT SITE OBSCURATION 100 VISIBILITY AT ACCIDENT SITE PRECIPITATION AT ACCIDENT SITE 3/4 MILE OR LESS NONE OBSTRUCTIONS TO VISION AT ACCIDENT SITE WIND DIRECTION-DEGREES GROUND FOG 220 WIND VELOCITY-KNOTS TYPE OF WEATHER CONDITIONS 8 IFR TYPE OF FLIGHT PLAN IFR | | | | | | |
| REMARKS- PLT TRANSITIONED FM VISUAL REFERENCE TO INSTRUMENT REFERENCE, ENCTR D GND FOG AFTER MDA. | | | | | | |

Full narrative is not available