NTSB Identification: MIA79FA021

14 CFR General Aviation Forn

Aircraft: CONVAIR 240, registration: LVMMR

| FILE | DATE | LOCATION | AIRCRAFT DATA | | RIES S M | | FLIGHT PURPOSE | PILOT DATA |
|--------|------------------------|----------|--|-------|-------------|---|-----------------------|---|
| E-0017 | 78/11/29 TIME - 112 | | CONVAIR 240 LVMMR DAMAGE-DESTROYED | 0 | 0 | 0 | INSTRUCTIONAL DUAL | AIRLINE TRANSPORT, AGE 34, 6500 TOTAL HOURS, 1249 IN TYPE, INSTRUMENT RATED. |

NAME OF AIRPORT - TAMIAMI
DEPARTURE POINT INTENDED DESTINATION
MIAMI,FL LOCAL
TYPE OF ACCIDENT PHASE OF OPERATION COLLISION WITH GROUND/WATER: CONTROLLED TAKEOFF: INITIAL CLIMB PROBABLE CAUSE(S)

PILOT IN COMMAND - INADEQUATE SUPERVISION OF FLIGHT DUAL STUDENT - IMPROPER OPERATION OF FLIGHT CONTROLS FACTOR(S)

MISCELLANEOUS ACTS, CONDITIONS - SIMULATED CONDITIONS

FIRE AFTER IMPACT

REMARKS- DUAL STUDENT LOST CONT ON SIM ENG OUT EMERGENCY.PIC NOT TYPE RATED IN ACFT

Full narrative is not available