

NTSB Identification: DCA78AA024

14 CFR Part 135 Nonscheduled operation of FRANCISCO CRUZ
Aircraft: BEECH D18S, registration: N500L

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-2965	78/9/26 TIME - 1845	SAN JUAN,PR	BEECH D18S N500L DAMAGE-DESTROYED	CR- 1 0 0 PX- 5 0 0 OT- 0 0 0	COMMERCIAL AIR TAXI-PASSG	COMMERCIAL, FL.INSTR., AGE 50, 4365 TOTAL HOURS, 46 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - SAN JUAN INTL						
DEPARTURE POINT		INTENDED DESTINATION				
BORINQUEN,PR		SAN JUAN,PR				
TYPE OF ACCIDENT			PHASE OF OPERATION			
TURBULENCE			LANDING: FINAL APPROACH			
COLLISION WITH GROUND/WATER: UNCONTROLLED			IN FLIGHT: UNCONTROLLED DESCENT			
PROBABLE CAUSE(S)						
PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES,DIRECTIVES,ETC.						
MISCELLANEOUS - VORTEX TURBULENCE						
FACTOR(S)						
INSTRUMENTS/EQUIPMENT AND ACCESSORIES - COMMUNICATIONS AND NAVIGATION EQUIPMENT: TRANSMITTERS AND/OR RECEIVERS						
FIRE AFTER IMPACT						
REMARKS- UNABLE TO COMMUNICATE ON TERMINAL RADAR SERVICE AREA FREQUENCY.						

Full narrative is not available