NTSB Identification: LAX78FA075

14 CFR Part 135 Scheduled operation of COCHISE AIRLNS Aircraft: CESSNA 402B, registration: N7866Q

| FILE | DATE L | OCATION | AIRCRAFT DATA | | | | | FLIGHT PURPOSE | PILOT DATA |
|--------|--|---------|----------------------|--------------------------|---|---|---|--|-----------------------|
| 3-4362 | 78/9/7 NR.HYDE TIME - 1323 | R,AZ | N7866Q | PX- | 0 | 0 | 1 | COMMERCIAL COMMUTER AIR CARRIER AIR TAXI-PASSG S-D | 45, 8289 TOTAL HOURS, |
| | DEPARTURE POINT | | INTENDED DESTINATION | | | | | | |
| | YUMA,AZ | | PHOENIX,AZ | | | | | | |
| | TYPE OF ACCIDENT | | | PHASE OF OPERATION | | | | | |
| | FIRE OR EXPLOSION: IN FLIGHT | | | IN FLIGHT: NORMAL CRUISE | | | | | |
| | PROBABLE CAUSE(S) | | | | | | | | |
| | PERSONNEL - MAINTENANCE,SERVICING,INSPECTION: IMPROPER MAINTENANCE (MAINTENANCE PERSONNEL) | | | | | | | | |
| | POWERPLANT - EXHAUST SYSTEM: OTHER | | | | | | | | |
| | MISCELLANEOUS ACTS,CONDITIONS - MISSING | | | | | | | | |
| | MISCELLANEOUS ACTS,CONDITIONS - VIBRATION,EXCESSIVE | | | | | | | | |
| | MISCELLANEOUS ACTS,CONDITIONS - FATIGUE FRACTURE | | | | | | | | |
| | MISCELLANEOUS ACTS,CONDITIONS - FIRE IN ENGINE | | | | | | | | |
| | EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND | | | | | | | | |
| | FIRE AFTER IMPACT | | | | | | | | |
| | REMARKS- BOLT CONNECTING BALL JOINT ON L ENG R SIDE FOUND MISSING. | | | | | | | | |
| | | | | | | | | | |

Full narrative is not available