

NTSB Identification: FTW78FA084

14 CFR Part 91 General Aviation
 Aircraft: GRUMMAN G-159, registration: N91G

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-3454	78/9/24 TIME - 1447	HOUSTON, TX	GRUMMAN G-159 N91G DAMAGE-DESTROYED	CR- 0 0 2 PX- 0 1 17 OT- 0 0 0	NONCOMMERCIAL CORP/EXEC	AIRLINE TRANSPORT, AGE 39, 10284 TOTAL HOURS, 955 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - HOUSTON HOBBY						
DEPARTURE POINT		INTENDED DESTINATION				
PONCA CITY, OK		HOUSTON, TX				
TYPE OF ACCIDENT				PHASE OF OPERATION		
ENGINE FAILURE OR MALFUNCTION				LANDING: GO-AROUND		
WHEELS-UP				LANDING: LEVEL OFF/TOUCHDOWN		
PROBABLE CAUSE(S)						
PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC.						
MISCELLANEOUS ACTS, CONDITIONS - IMPROPER EMERGENCY PROCEDURES						
FACTOR(S)						
MISCELLANEOUS ACTS, CONDITIONS - POORLY PLANNED APPROACH						
MISCELLANEOUS ACTS, CONDITIONS - FAILURE OF TWO OR MORE ENGINES						
MISCELLANEOUS ACTS, CONDITIONS - INTENTIONAL WHEELS-UP						
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE						
EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND						
REMARKS- R ENG SHUT DOWN IN FLT DUE LOW OIL PRES. R PROP NOT FULLY FEATHERED, L ENG NOT ABLE FULL ACCELERATE.						

Full narrative is not available