NTSB Identification: FTW79DRD16

14 CFR Part 91 General Aviation Aircraft: AERO COMM 520, registration: N4178B

| FILE | DATE LOCATION | | AIRCRAFT DATA | INJURIES F S M/N | | | FLIGHT PURPOSE | PILOT DATA | |
|--------|---|--|---|--|---|---|-------------------|---|---|
| 3-0536 | TIME - 1630 DEPARTURE POINT SOUTH BIMINI, BAHAMAS | | AERO COMM 520 N4178B DAMAGE-DESTROYED INTENDED DESTINATION TAMPICO,MEXICO | CR- PX- OT- | 0 | 0 | 0 | NONCOMMERCIAL PLEASURE/PERSONAL TRANSF | PRIVATE, AGE 30, 664 TOTAL HOURS, 12 IN TYPE, NOT INSTRUMENT RATED. |
| | TYPE OF ACCIDENT ENGINE FAILURE OR MALFUNCTION DITCHING PROBABLE CAUSE(S) | | | PHASE OF OPERATION IN FLIGHT: NORMAL CRUISE LANDING: LEVEL OFF/TOUCHDOWN | | | | | |
| | MISCELLANEOUS - UNDETERMINED COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON WATER | | | | | | | | |

Full narrative is not available