NTSB Identification: ANC79AA053

14 CFR Part 135 Nonscheduled operation of SEA AIRMOTIVE Aircraft: DEHAVND CAN DHC-4A, registration: N581PA

FILE	DATE	ATE LOCATION		AIRCRAFT DATA	INJ F	URI S			FLIGHT PURPOSE	PILOT DATA	
3-3926	79/5/25 TIME - 204	BULLEN POI	NT,AK	DEHAVND CAN DHC-4A N581PA DAMAGE-DESTROYED	PX-	0		0		AIRLINE TRANSPORT, AGE 53, 14738 TOTAL HOURS, 2630 IN TYPE, INSTRUMENT RATED.	
	NAME OF AIRPORT - BULLEN POINT										
	DEPARTURE	POINT	IN	TENDED DESTINATION							
	BULLEN P	OINT,AK	DEADHORSE,AK								
	TYPE OF ACCIDENT			•	PHASE OF OPERATION						
	STALL			TAKEOFF: INITIAL CLIMB							
	PROBABLE CAUSE(S)										
	PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING										
	PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC.										
	MISCELLANEOUS ACTS, CONDITIONS - CARGO SHIFTED										
	FACTOR(S)										
	PERSONNEL - OPERATIONAL SUPERVISORY PERSONNEL: INADEQUATE GROUND TRAINING-PROCEDURES FIRE AFTER IMPACT										
	REMARKS- ACFT CONFIGD FOR STOL DEP.CRASHED 1400FT FM START PT.STOL OPN NOT APPROVED.NEW LOADMASTER.										

Full narrative is not available