

# NTSB Identification: MIA80FA052

14 CFR Part 91 General Aviation  
Aircraft: CESSNA 414, registration: N1659T

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA	
				F	S	M/N			
3-1581	80/4/2 TIME - 1846	GULFPORT,MS	CESSNA 414	CR-	0	1	0	NONCOMMERCIAL	COMMERCIAL, AGE 32, 2670 TOTAL HOURS, 59 IN TYPE, INSTRUMENT RATED.
			N1659T	PX-	0	1	3	BUSINESS	
			DAMAGE-DESTROYED	OT-	0	0	0		
	NAME OF AIRPORT - GULFPORT-BILOXI								
	DEPARTURE POINT		INTENDED DESTINATION						
	GULFPORT,MS		GREENVILLE,MS						
	TYPE OF ACCIDENT				PHASE OF OPERATION				
	ENGINE FAILURE OR MALFUNCTION				TAKEOFF: INITIAL CLIMB				
	COLLISION WITH GROUND/WATER: CONTROLLED				TAKEOFF: INITIAL CLIMB				
	PROBABLE CAUSE(S)								
	POWERPLANT - MISCELLANEOUS: POWERPLANT FAILURE FOR UNDETERMINED REASONS								
	PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES,DIRECTIVES,ETC.								
	MISCELLANEOUS ACTS,CONDITIONS - IMPROPER EMERGENCY PROCEDURES								
	PARTIAL POWER LOSS - PARTIAL LOSS OF POWER - 1 ENGINE								
	EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND								
	REMARKS- R ENG LOST PWR,R PROP NOT FEATHERED.								

Full narrative is not available