

# NTSB Identification: ANC81DAA01

14 CFR Part 91 General Aviation  
Aircraft: BEECH E18S, registration: N333FL

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-2625	80/10/3 TIME - 0815	CANDLE,AK	BEECH E18S N333FL DAMAGE-SUBSTANTIAL	CR- PX- OT-	0 0 0	1 4 0	NONCOMMERCIAL CORP/EXEC	ATP, FLIGHT INSTR., AGE 27, 2660 TOTAL HOURS, 100 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - CANDLE NO.2								
DEPARTURE POINT		INTENDED DESTINATION						
CANDLE,AK		KOTZEBUE,AK						
TYPE OF ACCIDENT				PHASE OF OPERATION				
COLLIDED WITH: OBJECT				TAKEOFF: INITIAL CLIMB				
PROBABLE CAUSE(S)								
PILOT IN COMMAND - PREMATURE LIFT-OFF								
PILOT IN COMMAND - FAILED TO ABORT TAKEOFF								
FACTOR(S)								
AIRPORTS/AIRWAYS/FACILITIES - AIRPORT CONDITIONS: ICE/SLUSH ON RUNWAY								
MISCELLANEOUS ACTS, CONDITIONS - RAN OFF END OF RUNWAY								
REMARKS- UN TO LIFT OUT OF GND EFFECT. COLLIDED W BRUSH AT END OF RWY.								

Full narrative is not available