

NTSB Identification: NYC81FA056

14 CFR Part 135 Nonscheduled operation of AERO TAXI  
Aircraft: BEECH G18S, registration: N547DA

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA	
				F	S	M/N			
3-2017	81/6/12	NEW CUMBERLAND, PA	BEECH G18S	CR-	0	0	1	COMMERCIAL	COMMERCIAL, FL.INSTR., AGE 50, 7070 TOTAL HOURS, 1455 IN TYPE, INSTRUMENT RATED.
	TIME - 2222		N547DA	PX-	0	0	0	AIR TAXI-CARGO	
			DAMAGE-SUBSTANTIAL	OT-	0	0	0		
NAME OF AIRPORT - CAPITAL CITY									
DEPARTURE POINT		INTENDED DESTINATION							
NEW CUMBERLAND, PA		COLUMBUS, OH							
TYPE OF ACCIDENT				PHASE OF OPERATION					
ENGINE FAILURE OR MALFUNCTION				TAKEOFF: INITIAL CLIMB					
COLLIDED WITH: AUTOMOBILE				TAKEOFF: ABORTED					
PROBABLE CAUSE(S)									
POWERPLANT - ENGINE STRUCTURE: BLOWER, IMPELLER ASSEMBLY									
MISCELLANEOUS ACTS, CONDITIONS - MATERIAL FAILURE									
FACTOR(S)									
MISCELLANEOUS ACTS, CONDITIONS - RAN OFF END OF RUNWAY									
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE									
REMARKS- L ENG SUPERCHARGER, REAR BRG FAILED. STRUCK MOVING VEHICLE ON ROAD NR END OF RWY.									

Full narrative is not available