

NTSB Identification: LAX82DA017

14 CFR Part 91 General Aviation  
Aircraft: NITSUBISHI MU-2B, registration: N109TW

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-3415	81/11/22	NR.PAGO PAGO,A SAMOA	NITSUBISHI MU-2B	CR-	1	0 0	MISCELLANEOUS	COMMERCIAL, AGE 58,
	TIME - 1546		N109TW	PX-	0	0 0	FERRY	UNK/NR TOTAL HOURS,
			DAMAGE-DESTROYED	OT-	0	0 0		UNK/NR IN TYPE,
								INSTRUMENT RATED.
		DEPARTURE POINT	INTENDED DESTINATION					
		HONOLULU,HI	PAGO PAGO,AM SAMOA					
		TYPE OF ACCIDENT					PHASE OF OPERATION	
		ENGINE FAILURE OR MALFUNCTION					IN FLIGHT: NORMAL CRUISE	
		DITCHING					LANDING: LEVEL OFF/TOUCHDOWN	
		PROBABLE CAUSE(S)						
		MISC-FUEL STARVATION FOR UNDETERMINED REASON						
		MISCELLANEOUS ACTS,CONDITIONS - FUEL STARVATION						
		FACTOR(S)						
		MISCELLANEOUS ACTS,CONDITIONS - AIRCRAFT CAME TO REST IN WATER						
		EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON WATER						
		LOW ON FUEL						
		REMARKS- PLT STTD UN TRANS FUEL FM TIP TKS TO MAINS.SANK.						

Full narrative is not available