

DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OFFICER Navigation Cross Country OR COMMANDING OFFICER'S REPORT: Court of Inquiry NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE: 10-4-41 COMPOSITION: Plane crashed to ground AIRCRAFT CRASHED WHILE ATTEMPTING TO LAND President - Newcombe, C.F. - S/L DUE TO FAILURE OF STARBOARD ENGINE OR WAS - F/L Millar W.B. Member LOW FLYING AND FLEW INTO THE GROUND. - F/O Sharpe, E.W.C. Member RECOMMENDATIONS: 1. That orders relative to low flying be redrafted in conformity with CAP 100. PRIMARY CAUSE: 2. That wearing of parachute harness be strictly Cause-of accident obscure enforced in accordance with CAP 100 3. That low flying orders, as re-drafted, be strictly enforced and that all personned affected by such /orders be required (A) DISCIPLINARY (B) TECHNICAL (C) OTHER to read them and to /acknowledge in writing having done so, and that /such orders are thoroughly understood. Such /written acknowledgement to refer definitely to the orders signed for. SECONDARY CAUSE OR CONTRIBUTING FACTORS: Aircraft hit trees damaging port wing and then flew for about a RECORDED BY DATE mile at approx. 100 ft above ground and crashed. CHECKED BY DATE